



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

List of New Products

PP+EPDM

<p>418PSW18LR NEW</p> <p>48571-52R00-P</p> <p>SWIFT (2018)</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p>		<p>A14PMG516F NEW</p> <p>10091668-P</p> <p>MG5</p> <p>Shock Dust Cover (FR, PP+EPDM) B : 2 / C : 40 pcs.</p>	
<p>T18PZE21LR NEW</p> <p>45535-09560-P</p> <p>ALTIS (2019) ZRE210, ZRE211</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p>		<p>S14PXV11E0 NEW</p> <p>20372SC000-P</p> <p>XV (2011)</p> <p>Shock Dust Cover (RE, PP+EPDM) B : 2 / C : 40 pcs.</p>	

TPEE

<p>O17P304UZ NEW</p> <p>44018-T9A-T91-P</p> <p>CITY, JAZZ (2009-2014)</p> <p>Drive Shaft Boot (OUTER M/T, TPEE) B : 1 / C : 44 pcs.</p>		<p>O17P003UZ NEW</p> <p>44018-SDE-T00-P, 44333-SDE-T01-P</p> <p>ACCORD (2003, 2013), CIVIC (2006)</p> <p>Drive Shaft Boot (OUTER, TPEE) B : 1 / C : 44 pcs.</p>	
--	--	--	--

Control Arm

<p>T24ANC93WL NEW</p> <p>48069-09071-ARM</p> <p>VIOS NCP93, YARIS NCP91</p> <p>Control Arm (LH) B : 1 / C : 1 pcs.</p>		<p>T24ANC93WR NEW</p> <p>48068-09071-ARM</p> <p>VIOS NCP93, YARIS NCP91</p> <p>Control Arm (RH) B : 1 / C : 1 pcs.</p>	
---	--	---	--

FORD

<p>128RG15W0 NEW</p> <p>EB3C3A016AA</p> <p>RANGER (2015)</p> <p>Bumper Bound (LOWER) B : 4 / C : 48 pcs.</p>		
---	--	--



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

MG

<p>A14HS19E0 NEW</p> <p>10525151, 10525152</p> <p>MG HS (2019)</p> <p>Shock Dust Cover (RE)</p>		<p>A14M314E1 NEW</p> <p>10039881</p> <p>MG3 (2014)</p> <p>Shock Absorber Bumper (RE)</p>	
<p>A21M516F NEW</p> <p>50016118</p> <p>MG5 (2016)</p> <p>Stabilizer Shaft Rubber (FR)</p>		<p>A21ZS17F NEW</p> <p>10227886</p> <p>MG ZS (2017)</p> <p>Stabilizer Shaft Rubber (FR)</p>	
<p>A24M614WB NEW</p> <p>30020135, 30020136, 30020138</p> <p>MG6 (2014)</p> <p>Lower Arm Bushing (LH, RH BIG)</p>		<p>A25M61433 NEW</p> <p>30022933</p> <p>MG6 (2014)</p> <p>Suspension Bush (RE, SMALL)</p>	
<p>A25M614PG NEW</p> <p>30000171</p> <p>MG6 (2014)</p> <p>Suspension Bush (RE UP, LONG)</p>		<p>A27HS19E NEW</p> <p>10094355</p> <p>MG HS (2019)</p> <p>Link Assy (RE)</p>	
<p>A27HS19FLR NEW</p> <p>10523751</p> <p>MG HS (2019)</p> <p>Link Assy (FR LH, RH)</p>		<p>A27M314F NEW</p> <p>30003601</p> <p>MG3 (2014)</p> <p>Link Assy (FR)</p>	

SUBARU

<p>S21XV11E NEW</p> <p>20464SC010</p> <p>XV (2011)</p> <p>Stabilizer Shaft Rubber (RE)</p>		<p>S21XV11F NEW</p> <p>20414AG070</p> <p>XV (2011)</p> <p>Stabilizer Shaft Rubber (FR)</p>	
<p>S27XV11F0 NEW</p> <p>20470SA001</p> <p>SUBARU XV (2011)</p> <p>Link Assy (FR LH, RH)</p>			







RUBBER INTERTRADE CO., LTD.






Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

List of New Products


MAZDA

<p>D14CX17E0 NEW</p> <p>KB7W 28 1A0</p> <p>CX5 (2017)</p> <p>Shock Dust Cover (RE)</p>  <p>B : 2 / C : 12 pcs.</p>	<p>D14CX17F1 NEW</p> <p>KB7W 34 111</p> <p>CX5 (2017)</p> <p>Shock Absorber Bumper (FR)</p>  <p>B : 6 / C : 72 pcs.</p>
<p>D26X316E0 NEW</p> <p>DD1V 28 700G-0</p> <p>CX3 (2016)</p> <p>Shock Absorber Bush (RE)</p>  <p>B : 10 / C : 180 pcs.</p>	<p>D27M319F0 NEW</p> <p>BCKE 34 170</p> <p>MAZDA3 (2019), CX-30 (2020) DM</p> <p>Link Assy (FR LH, RH)</p>  <p>B : 2 / C : 40 pcs.</p>

TOYOTA

<p>T24GD30WB NEW</p> <p>48068-26180-1, 48069-26180-1, 48655-26010</p> <p>GDH 300</p> <p>Lower Arm Bushing (BIG)</p>  <p>B : 2 / C : 36 pcs.</p>	<p>T24GD30WS NEW</p> <p>48069-26180-2, 48654-26030</p> <p>COMMUTER, MAJESTY (2019)</p> <p>GDH300, HIACE (2019) GDH322</p> <p>Lower Arm Bushing (SMALL)</p>  <p>B : 4 / C : 72 pcs.</p>
<p>T26CC20E0 NEW</p> <p>48530-0A050-0</p> <p>COROLLA CROSS (2020)</p> <p>Shock Absorber Bush (RE)</p>  <p>B : 8 / C : 144 pcs.</p>	<p>T27ST17F NEW</p> <p>48820-0D040</p> <p>SIENTA NSP170</p> <p>Link Assy (FR)</p>  <p>B : 2 / C : 36 pcs.</p>
<p>T28GD30E0 NEW</p> <p>48341-26290</p> <p>COMMUTER, MAJESTY (2019)</p> <p>GDH300, HIACE (2019) GDH322</p> <p>Bumper Bound (RE)</p>  <p>B : 2 / C : 24 pcs.</p>	

NISSAN













<p>N27Y62FL NEW</p> <p>54668-1LB0A</p> <p>PATROL Y62 (2013)</p> <p>Link Assy (FR, LH)</p>  <p>B : 2 / C : 54 pcs.</p>	<p>N27Y62FR NEW</p> <p>54618-1LB0A</p> <p>PATROL Y62 (2013)</p> <p>Link Assy (FR, RH)</p>  <p>B : 2 / C : 54 pcs.</p>
---	---



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

HONDA




<p>O13216F0 NEW</p> <p>51670-TEA-T01</p> <p>CIVIC (2016)</p> <p>Shock Absorber Mounting (FR)</p>  <p>B : 1 / C : 20 pcs.</p>	<p>O13417F0 NEW</p> <p>51670-TMJ-T01</p> <p>CRV (2017)</p> <p>Shock Absorber Mounting (FR)</p>  <p>B : 1 / C : 20 pcs.</p>
<p>O14019E1 NEW</p> <p>52722-TVA-A01</p> <p>ACCORD (2019)</p> <p>Shock Absorber Bumper (RE LH, RH)</p>  <p>B : 6 / C : 72 pcs.</p>	<p>O14320F1 NEW</p> <p>51722-T00-T01</p> <p>CITY (2020)</p> <p>Shock Absorber Bumper (FR)</p>  <p>B : 6 / C : 72 pcs.</p>
<p>O21216E NEW</p> <p>52300-TEA-T01-0</p> <p>CIVIC (2016)</p> <p>Stabilizer Shaft Rubber (RE)</p>  <p>B : 16 / C : 384 pcs.</p>	<p>O21417F NEW</p> <p>51300-TMJ-T52-0</p> <p>CRV (2017)</p> <p>Stabilizer Shaft Rubber (FR)</p>  <p>B : 8 / C : 192 pcs.</p>
<p>O21M014F NEW</p> <p>51306-TE7-K02</p> <p>MOBILIO (2014)</p> <p>Stabilizer Shaft Rubber (FR)</p>  <p>B : 12 / C : 288 pcs.</p>	<p>O26008E0 NEW</p> <p>53685-TA0-A01</p> <p>ACCORD (2008)</p> <p>Grommet Steering Bush (RH)</p>  <p>B : 10 / C : 180 pcs.</p>
<p>O26206R0 NEW</p> <p>53685-SNA-A01</p> <p>CIVIC (2006) HPS</p> <p>Grommet Steering Bush (RH)</p>  <p>B : 10 / C : 180 pcs.</p>	<p>O26304E0 NEW</p> <p>53686-TF0-003</p> <p>CITY (2008), JAZZ (2009), BR-V (2016)</p> <p>Grommet Steering Bush (RE)</p>  <p>B : 10 / C : 180 pcs.</p>
<p>O27320FL NEW</p> <p>51325-T00-T01</p> <p>CITY (2020)</p> <p>Link Assy (FR, LH)</p>  <p>B : 2 / C : 32 pcs.</p>	<p>O27320FR NEW</p> <p>51320-T00-T01</p> <p>CITY (2020)</p> <p>Link Assy (FR, RH)</p>  <p>B : 2 / C : 32 pcs.</p>







RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

ISUZU

<p>I2747202F0</p> <p>8-97484776-0</p> <p>D-MAX (2020) (2WD)</p> <p>Link Assy (FR, LH, RH)</p>	<p>NEW</p>  <p>B : 2 / C : 90 pcs.</p>
<p>I2747204FL</p> <p>8-98390135-0</p> <p>D-MAX (2020) (4WD)</p> <p>Link Assy (FR, LH)</p>	<p>NEW</p>  <p>B : 2 / C : 54 pcs.</p>
<p>I2747204FR</p> <p>8-98390134-0</p> <p>D-MAX (2020) (4WD)</p> <p>Link Assy (FR, RH)</p>	<p>NEW</p>  <p>B : 2 / C : 54 pcs.</p>

MITSUBISHI

<p>M20TT15ET</p> <p>4152A020</p> <p>TRITON (2015)</p> <p>Spring Shackle Rubber (RE SHORT)</p>	<p>NEW</p>  <p>B : 20 / C : 480 pcs.</p>
<p>M25NA4183</p> <p>4100A018-3, MR594429</p> <p>SPACE WAGON NA4</p> <p>Suspension Bush (RE)</p>	<p>NEW</p>  <p>B : 2 / C : 36 pcs.</p>
<p>M25XP18E0</p> <p>4120A266-0</p> <p>XPANDER (2018) NC1W</p> <p>Suspension Bush (RE)</p>	<p>NEW</p>  <p>B : 2 / C : 32 pcs.</p>
<p>M25NA4ES0</p> <p>MN103487-0</p> <p>SPACE WAGON NA4</p> <p>Suspension Bush (RE)</p>	<p>NEW</p>  <p>B : 6 / C : 108 pcs.</p>