



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

PP+EPDM

<p>A18PM5LR 10045281-P MG5 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>A18PM617LR QFWS0011A-P MG6 (2014) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
	<p>A14PHS19F0 10401261-P MG HS (2019) Shock Dust Cover (FR, PP+EPDM) B : 2 / C : 40 pcs.</p> 
<p>A14PZS17E0 50016198-P MG ZS (2017) Shock Dust Cover (RE, PP+EPDM) B : 2 / C : 12 pcs.</p> 	<p>A14PZS17F0 10290508-P MG ZS (2017) Shock Dust Cover (FR, PP+EPDM) B : 2 / C : 40 pcs.</p> 
<p>D18PCX12LR KD31 32 12X-P CX5 (2012), MAZDA3 (2013), BM, BN Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>D18PM2140 D09H-32-12X-P MAZDA2 (2014), CX3 (2015), CX9 (2016) Steering Gear Boot (PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>D18PBT50LR UC2M 32 12X-P BT50 PRO Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	
<p>H18PH10LR 57740-4H000-P HYUNDAI H1 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	
<p>I18P47120 8-97945423-1-P D-MAX (2012) (4WD) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>I18P4720LR 8-98055745-0-P D-MAX (2012) (2WD) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>M18PXP18LR 4410A959-P XPANDER NC1W (2018) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>N18PJU10LR D8203-1KE1A-P JUKE F15 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

PP+EPDM















<p>N18PE26LR D8203-3XA0A-P NV350, E26 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>N18PN170 D8203-1HA0A-P SUNNY N17 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>N18PT32LR D8203-4BA0A-P X-TRAIL T32, QASHQAI J11 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>N18PY62 D8203-1LB0A-P PATROL Y62 Steering Gear Boot (PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>N18PT31LR 48203-JD01A-P X-TRAIL T31, QASHQAI J10, J11 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>N18PNR40Z 48203-EB70A-P, D8203-EB70A-P NAVARA D40T Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>O18P309LR 53429-TF0-003-P JAZZ, CITY, BRIO (2009) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	
<p>O18P014LR 53429-T2B-A01-P ACCORD HYBRID (2014) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>O18P414LR 53429-T0A-A01-P CRV (2014), FREED (2010) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>O14P216E0 52688-TBA-A01-P CIVIC (2016) Shock Dust Cover (RE, PP+EPDM) B : 2 / C : 12 pcs.</p> 	<p>O14P216F 51686-TBA-A01-P CIVIC (2016) Shock Dust Cover (FR, PP+EPDM) B : 2 / C : 12 pcs.</p> 
<p>O14P417E0 52688-TMJ-T02-P CRV (2017) Shock Dust Dover (RE, PP+EPDM) B : 2 / C : 12 pcs.</p> 	<p>O18P216LR 53429-TBA-A01-P CIVIC (2016) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>S18PXV17LR 34137FE020-P SUBARU XV (2017) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	



RUBBER INTERTRADE CO., LTD.












Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

PP+EPDM

<p>T18PRV02LR 45535-09380-P REVO (2WD) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PRV04LR 45535-09390-P REVO (4WD) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>T18PST16LR 45535-09330-P SIENTA NSP170 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PUZ10Z 45535-60010-P FZJ100, HDJ100, UZJ100 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>T18PNC30Z 45535-59035-P YARIS NCP9#, NCP13# Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	
<p>T18PGR15L 45535-69015-P LEXUS GX460, URJ150, PRADO, KDJ15#, GDJ15# Steering Gear Boot (LH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PGR15R 45535-69025-P LEXUS GX460, URJ150, PRADO, KDJ15#, GDJ15# Steering Gear Boot (RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>T18PGS45 45535-49035-P GSU45 (2007-2013) Steering Gear Boot (PP+EPDM) B : 2 / C : 50 pcs.</p> 	
<p>T18PAH20LR 45535-59005-P ALPHARD ANH20, ATH20, GGH20 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PCH18LR 45535-59075-P C-HR (2018) Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>T18PAC30LR 45535-28030-P ESTIMA ACR30 (2000-2006), ALPHARD ANH1#, MHN1# Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PAGZLR 45535-49045-P LEXUS NX300H/NX200T, RAV4 ASA4# Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>T18PC051Z 45535-30030-P, 59045-P, 59065-P CAMRY HYBRID AHV40, LEXUS AWL10, ALE20, GRS190, GRS202 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PF65LR 45535-BZ070-P AVANZA F651, F652 Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 



PP+EPDM

<p>T18PPW30LR</p> <p>45535-49015-P</p> <p>LEXUS CT200H, PRIUS ZVW30</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	
<p>T18PGD30LR</p> <p>45535-29045-P</p> <p>HIACE GDH300</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PPW20LR</p> <p>45535-52060-P</p> <p>PRIUS NHW20</p> <p>Steering Gear Boot LH, RH (PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>T18PC07LR</p> <p>45535-09250-P</p> <p>CAMRY (2012) ACV51, ASV50, AVV50</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PZE1410</p> <p>45535-09110-P</p> <p>ALTIS ZZE141,142, ZRE171</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>T18PCR19LR</p> <p>45535-29025-P</p> <p>CAMRY (2019) ASV71, AXVA70, AXVH71</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>T18PF60LR</p> <p>45535-BZ010-P</p> <p>AVANZA F601</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 
<p>418PSW18LR NEW</p> <p>48571-52R00-P</p> <p>SWIFT (2018)</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>A14PMG516F NEW</p> <p>10091668-P</p> <p>MG5</p> <p>Shock Dust Cover (FR, PP+EPDM) B : 2 / C : 40 pcs.</p> 
<p>T18PZE21LR NEW</p> <p>45535-09560-P</p> <p>ALTIS (2019) ZRE210, ZRE211</p> <p>Steering Gear Boot (LH, RH, PP+EPDM) B : 2 / C : 50 pcs.</p> 	<p>S14PXV11E0 NEW</p> <p>20372SC000-P</p> <p>XV (2011)</p> <p>Shock Dust Cover (RE, PP+EPDM) B : 2 / C : 40 pcs.</p> 



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

TPEE

<p>D17PBT54U PP01 22 530-P BT50 (4WD) Drive Shaft Boot (OUTER, TPEE)</p>	<p>D17PCX12FU GG62 22 530-P MAZDA3 (2011) BL (2.0 cc), CX5 (2012) (B) Drive Shaft Boot (FR, OUTER, TPEE)</p>
<p>D17PM313UZ FTC3 22 530-P MAZDA3 (2013) Drive Shaft Boot (OUTER, TPEE)</p>	<p>D17PMZ2UM FD80 22 530A-P MAZDA2, FIESTA Drive Shaft Boot (M/T, OUTER, TPEE)</p>
<p>D17PMZ3UZ FG01 22 530-P, FG02 22 530-P, GG25 22 530-P MAZDA3 (2003-2008) (1.6,2.0 cc) Drive Shaft Boot (A/T, M/T, OUTER, TPEE)</p>	<p>D17PT20UF GG15 22 530-P TRIBUTE (3.0 cc), ESCAPE Drive Shaft Boot (FR, OUTER, TPEE)</p>
<p>D17PMZ2UA FA81 22 530A-P MAZDA2, FIESTA Drive Shaft Boot (A/T, OUTER, TPEE)</p>	
<p>D17PCX12DFU FTB4 22 530-P CX5 (2012) (D) Drive Shaft Boot (FR, OUTER, TPEE)</p>	<p>D17PCX12EU RTA1 22 530-P CX5 (2012) (4WD) Drive Shaft Boot (RE, OUTER, TPEE)</p>
<p>D17PT20IZ GD29 22 540-P TRIBUTE, ESCAPE Drive Shaft Boot (RE, INNER, TPEE)</p>	<p>D17PT20UE GD29 22 530-P TRIBUTE, ESCAPE Drive Shaft Boot (RE, OUTER, TPEE)</p>



TPEE

<p>N17PJ32UZ 39241-9Y085-P, 9Y086-P, C924A-9Y015-P TEANA (2009) J32, SYLPHY B17, PULSAR C12 (1.6 CC) Drive Shaft Boot (OUTER, M/T, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	<p>N17PK13UZ C9241-1HC1B-P MARCH K13 Drive Shaft Boot (A/T, M/T, OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>
<p>N17PTI10UZ C9241-EE70A-P, C9B41-CG000-P TIIDA C11, LATIO SC11 (1.6 cc), SYLPHY B17, PULSAR C12 (1.6 cc) Drive Shaft Boot (OUTER A/T, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	<p>N17PTI11UZ C9241-EE76A-P, EW60K-P, 39241-EW60K-P TIIDA C11, LATIO SC11 (1.8 cc), SYLPHY B17, PULSAR C12 (1.8 cc), (1.6 cc TURBO) Drive Shaft Boot (OUTER, A/T, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>
<p>N17PNR40UZ 39241-EA027-P NAVARA D40T (4WD) Drive Shaft Boot (OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	
<p>O17P003UZ NEW 44018-SDE-T00-P, 44333-SDE-T01-P ACCORD (2003, 2013), CIVIC (2006) Drive Shaft Boot (OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	
<p>O17P206UZ 44333-SEL-T01-P CIVIC (2006) (1.8 cc) Drive Shaft Boot (OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	<p>O17P212UZ 44018-TF6-N13-P, 44333-TF0-003-P CIVIC (2012) (1.8 cc) Drive Shaft Boot (A/T, OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>
<p>O17P2120UZ 44018-TR0-J90-P, 44333-TS6-H91-P CIVIC (2012) (1.8 M/T), (2.0 A/T) Drive Shaft Boot (OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	<p>O17P304UZ NEW 44018-T9A-T91-P CITY, JAZZ (2009-2014) Drive Shaft Boot (OUTER M/T, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>
<p>O17P407E 42017-SWE-000-P, 42315-SWE-003-P CRV (2007) G3, (2013) G4 Drive Shaft Boot (RE, INNER, OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	<p>O17P414UZ 44333-TL1-E01-P CRV (2014) Drive Shaft Boot (OUTER, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>
<p>O17P515UZ 44018-T7W-315-P, T7W-A02-P, TE7-K51-P HR-V (2015), BR-V (2016) Drive Shaft Boot (OUTER, LH, RH, TPEE)</p>  <p>B : 1 / C : 44 pcs.</p>	



TPEE

<p>T17PC04UZ 43447-06120-P CAMRY ACV30, 31 Drive Shaft Boot (OUTER, TPEE)</p>	<p>T17PC05UZ 43447-06350-P CAMRY ACV40 Drive Shaft Boot (OUTER, TPEE)</p>
<p>T17PC06UZ 43447-06441-P CAMRY (2012) ACV50, ACV51, ASV50 Drive Shaft Boot (OUTER, TPEE)</p>	<p>T17PKD12UZ 43447-60130-P, 60141-P KDJ120, KDJ150, GRJ120, GRJ150 Drive Shaft Boot (OUTER, TPEE)</p>
<p>T17PUR2IZ 43448-60092-P LAND CRUISER URJ20# VDJ200 Drive Shaft Boot (INNER, TPEE)</p>	<p>T17PUR2UZ 43447-60092-P LAND CRUISER URJ20# VDJ200 Drive Shaft Boot (OUTER, TPEE)</p>
<p>T17PNC50UZ 43447-0D350-P VIOS NCP150, YARIS NSP152, ETIOS Drive Shaft Boot (OUTER, TPEE)</p>	<p>T17PZ14UZ 43447-12050-P ALTIS ZZE141 Drive Shaft Boot (OUTER, TPEE)</p>
<p>T17PNC93UZ 43447-52011-P VIOS NCP93 Drive Shaft Boot (OUTER, TPEE)</p>	<p>T17PYA91UZ 43447-0D140-P YARIS NCP91 Drive Shaft Boot (OUTER, TPEE)</p>
<p>T17PZJ95UZ 43447-35040-P PRADO VZJ95 Drive Shaft Boot (OUTER, TPEE)</p>	<p>T19PRV020 37334-0K020-P REVO Drive Shaft Boot (TPEE)</p>



Shock Absorber Bearing

<p>D13BMZ2F D651 34 38XA MAZDA2 (2007) DE, FIESTA, ECOSPORT Shock Absorber Bearing (FR)</p>		<p>D13BMZ3F BBM2 34 38X MAZDA3 Shock Absorber Bearing (FR)</p>	
<p>D13BCX12F KR27 34 38X CX5 (2012), MAZDA3 (2013) Shock Absorber Bearing (FR)</p>			
<p>H13BH10F 54612-4D000 HYUNDAI H1 Shock Absorber Bearing (FR)</p>			
<p>M13BA03F 4060A446 MIRAGE, ATTRAGE A03, A13 Shock Absorber Bearing (FR)</p>		<p>M13BCY30F MR272946 LANCER EX CY3, CY4, CS9 Shock Absorber Bearing (FR)</p>	
<p>N13BA32F 54325-5V000 A32 Shock Absorber Bearing (FR)</p>		<p>N13BB17F 54325-1KA0A SYLPHY B17 (2013), PULSAR C12 (2013), X-TRAIL T31 (2010) Shock Absorber Bearing (FR)</p>	
<p>N13BJ32F 54325-JA00A TEANA J32, L33 Shock Absorber Bearing (FR)</p>		<p>N13BN16F 54325-4M400 N16 Shock Absorber Bearing (FR)</p>	
<p>N13BT31F0 54325-8271R X-TRAIL T32 Shock Absorber Bearing (FR, LH, RH)</p>		<p>N13BTI11F0 54325-ED00A, ED02A TIIDA C11, LATIO SC11, LIVINA L11N Shock Absorber Bearing (FR)</p>	
<p>N13BK13F 54325-1HA0A, 48619-0D011, 51726-SAA-013,003, 51726-SFA-005 MARCH 10, ALMERA 11,20, NOTE, VIOS 07, YARIS 07, CITY 03,06,08,14,20, JAZZ 04,09,15, HR-V 15,21, BRIO, AMAZE 11, BR-V 16, FREED 10 Shock Absorber Bearing (FR)</p>			



Shock Absorber Bearing

<p>O13B201F</p> <p>51726-S5A-004</p> <p>CIVIC (2002), CRV (2002)</p> <p>Shock Absorber Bearing (FR)</p>		<p>O13B202F</p> <p>51726-S5A-701</p> <p>CIVIC (2002), CRV (2003)</p> <p>Shock Absorber Bearing (FR)</p>	
<p>O13B206F</p> <p>51726-SNA-013, G01</p> <p>CIVIC (2006)</p> <p>Shock Absorber Bearing (FR)</p>		<p>O13B212F</p> <p>51726-TR0-A01</p> <p>CIVIC (2012)</p> <p>Shock Absorber Bearing (FR)</p>	
<p>O13B407F</p> <p>51726-STK-A01</p> <p>CRV (2007-2011)</p> <p>Shock Absorber Bearing (FR)</p>		<p>O13B013F</p> <p>51726-T3V-A01</p> <p>ACCORD (2013)</p> <p>Shock Absorber Bearing (FR)</p>	
<p>O13B216F</p> <p>51726-TBA-A01</p> <p>CIVIC (2016)</p> <p>Shock Absorber Bearing (FR)</p>		<p>O13BSW10F</p> <p>51726-SLJ-J02</p> <p>STEP WAGON, SPADA (2010-2015)</p> <p>Shock Absorber Bearing (FR)</p>	
<p>S13BRC41F</p> <p>41710-80G00, 41710-80G10 41741-50E00, 41741-83E00</p> <p>WAGON R + RC410, 413</p> <p>Shock Absorber Bearing</p>		<p>T13BCH18F</p> <p>48619-F4010</p> <p>C-HR (2018), ALTIS (2020)</p> <p>Shock Absorber Bearing (FR)</p>	
<p>T13BNC50F</p> <p>48619-52030</p> <p>VIOS NCP150, YARIS NSP152</p> <p>Shock Absorber Bearing (FR)</p>		<p>T13BAH20F</p> <p>48619-28010</p> <p>ALPHARD AHR20, ANH20, ASTIMA AHR20</p> <p>Shock Absorber Bearing (FR)</p>	
<p>A13BHS19F</p> <p>10401259</p> <p>MG HS (2019)</p> <p>Shock Absorber Bearing (FR)</p>		<p>A13BZS17F</p> <p>10244443</p> <p>MG ZS (2017)</p> <p>Shock Absorber Bearing (FR)</p>	
<p>T13BC04F</p> <p>90903-63014</p> <p>CAMRY (1993) SXV10, (1998) SXV20, (2002) ACV30, (2007) ACV40, (2012) ACV50, ACV51, ASV50, AVV50, ALPHARD (2002) MNH10</p> <p>Shock Absorber Bearing (FR)</p>			



CONTROL ARM

<p>O24A003WL</p> <p>51360-SDA-A03-ARM</p> <p>ACCORD (2003)</p> <p>Control Arm (LOW, LH)</p>		<p>O24A003WR</p> <p>51350-SDA-A03-ARM</p> <p>ACCORD (2003)</p> <p>Control Arm (LOW, RH)</p>	
<p>O24A008PL</p> <p>51520-TA0-A03-ARM</p> <p>ACCORD (2008)</p> <p>Control Arm (UP, LH)</p>		<p>O24A008PR</p> <p>51510-TA0-A03-ARM</p> <p>ACCORD (2008)</p> <p>Control Arm (UP, RH)</p>	
<p>O24A008WL</p> <p>51360-TA0-A00-ARM</p> <p>ACCORD (2008)</p> <p>Control Arm (LOW, LH)</p>		<p>O24A008WR</p> <p>51350-TA0-A00-ARM</p> <p>ACCORD (2008)</p> <p>Control Arm (LOW, RH)</p>	
<p>O24A201WL</p> <p>51360-S5A-030-ARM</p> <p>CIVIC (2001)</p> <p>Control Arm (LOW, LH)</p>		<p>O24A201WR</p> <p>51350-S5A-030-ARM</p> <p>CIVIC (2001)</p> <p>Control Arm (LOW, RH)</p>	
<p>O24A206WL</p> <p>51360-SNA-903-ARM</p> <p>CIVIC (2006)</p> <p>Control Arm (LOW, LH)</p>		<p>O24A206WR</p> <p>51350-SNA-903-ARM</p> <p>CIVIC (2006)</p> <p>Control Arm (LOW, RH)</p>	
<p>O24A302WL</p> <p>51360-SEL-T01-ARM</p> <p>CITY (2003,2006), JAZZ (2004,2006)</p> <p>Control Arm (LOW, LH)</p>		<p>O24A302WR</p> <p>51350-SEL-T01-ARM</p> <p>CITY (2003,2006), JAZZ (2004,2006)</p> <p>Control Arm (LOW, RH)</p>	
<p>O24A304WL</p> <p>51360-TG0, TG1-T02-ARM</p> <p>CITY (2008) G3, JAZZ (2009) GE, G2, BRIO, AMAZE (2011)</p> <p>Control Arm (LOW, LH)</p>		<p>O24A304WR</p> <p>51350-TG0, TG1-T02-ARM</p> <p>CITY (2008) G3, JAZZ (2009) GE, G2, BRIO, AMAZE (2011)</p> <p>Control Arm (LOW, RH)</p>	









CONTROL ARM

<p>T24AC04WL</p> <p>48069-33050-ARM, 33060, 33070 CAMRY ACV30, ACV40, ACV50, ACV51 Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AC04WR</p> <p>48068-33050-ARM, 33060, 33070 CAMRY ACV30, ACV40, ACV50, ACV51 Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24AGR15KL</p> <p>48069-60050-ARM, 60051-ARM PRADO KDJ150 (KDSS) Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AGR15KR</p> <p>48068-60050-ARM, 60051-ARM PRADO KDJ150 (KDSS) Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24AGR15WL</p> <p>48069-60040-ARM PRADO KDJ150 Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AGR15WR</p> <p>48068-60040-ARM PRADO KDJ150 Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24AGR21PL</p> <p>48630-60040-ARM GRN215, GSJ10, GRJ120 Control Arm (UP, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AGR21PR</p> <p>48610-60070-ARM GRN215, GSJ10, GRJ120 Control Arm (UP, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24AGR21WL</p> <p>48069-60010-ARM GRN215, GSJ10, GRJ120 Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AGR21WR</p> <p>48068-60010-ARM GRN215, GSJ10, GRJ120 Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24AKD20PL</p> <p>48067-29215-ARM KDH200 Control Arm (UP, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AKD20PR</p> <p>48066-29215-ARM KDH200 Control Arm (UP, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24ANC42WL</p> <p>48069-09010-ARM VIOS NCP42, ECHO Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24ANC42WR</p> <p>48068-09010-ARM VIOS NCP42, ECHO Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24ANC50WL</p> <p>48069-09240-ARM VIOS NCP150, YARIS NSP152, SIENTA NSP170, ETIOS Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24ANC50WR</p> <p>48068-09230-ARM VIOS NCP150, YARIS NSP152, SIENTA NSP170, ETIOS Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>



CONTROL ARM

<p>T24AVG02WL</p> <p>48069-0K010-ARM</p> <p>VIGO (2WD)</p> <p>Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AVG02WR</p> <p>48068-0K010-ARM</p> <p>VIGO (2WD)</p> <p>Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24AZ12WL</p> <p>48069-02210-ARM</p> <p>ALTIS ZZE121, 122, 141, ZRE171, 172</p> <p>Control Arm (LOW, LH)</p>  <p>B : 1 / C : 1 pc.</p>	<p>T24AZ12WR</p> <p>48068-02210-ARM</p> <p>ALTIS ZZE121, 122, 141, ZRE171, 172</p> <p>Control Arm (LOW, RH)</p>  <p>B : 1 / C : 1 pc.</p>
<p>T24ANC93WL</p> <p>48069-09071-ARM</p> <p>VIOS NCP93, YARIS NCP91</p> <p>Control Arm (LH)</p>  <p>B : 1 / C : 1 pcs.</p>	<p>T24ANC93WR</p> <p>48068-09071-ARM</p> <p>VIOS NCP93, YARIS NCP91</p> <p>Control Arm (RH)</p>  <p>B : 1 / C : 1 pcs.</p>



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

FORD

<p>117RG18IZ JB3Z3B436A-I RANGER (2018) Drive Shaft Boot (INNER)</p>		<p>B : 2 / C : 100 pcs.</p>	<p>117RG18UZ JB3Z3B436A-U RANGER (2018) Drive Shaft Boot (OUTER)</p>		<p>B : 2 / C : 100 pcs.</p>
<p>120RG18EG AB315719AC RANGER (2018) Spring Shackle Rubber (RE, LONG)</p>		<p>B : 12 / C : 288 pcs.</p>	<p>120RG18ET AB315719BC RANGER (2018) Spring Shackle Rubber (RE, SHORT)</p>		<p>B : 16 / C : 384 pcs.</p>
<p>121RG18F JB3C5484BB RANGER (2.0 cc) (2018) Stabilizer Shaft Rubber (FR)</p>		<p>B : 8 / C : 128 pcs.</p>			
<p>124ES13WS GN153063AA, GN1Z3079B-2 ECOSPORT (2013) Lower Arm Bushing (SMALL)</p>		<p>B : 6 / C : 108 pcs.</p>	<p>124RG18P AB313068BB RANGER (2.0 cc) (2018) Upper Arm Bushing</p>		<p>B : 6 / C : 108 pcs.</p>
<p>126RG180 JB3Z18124L-0 RANGER (2018) Shock Absorber Bush</p>		<p>B : 6 / C : 108 pcs.</p>			
<p>127RG18F JB3C3052AA RANGER (2018) (2.0 cc) Link Assy (FR)</p>		<p>B : 2 / C : 36 pcs.</p>			
<p>128RG18E AB315K570BC RANGER (2.0 cc) (2011-2018) Bumper Bound (RE)</p>		<p>B : 4 / C : 48 pcs.</p>	<p>128RG15W0 EB3C3A016AA RANGER (2015) Bumper Bound (LOWER)</p>		<p>B : 4 / C : 48 pcs.</p>



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

MG













<p>A14HS19F 10486951 MG HS (2019) Shock Absorber Bumper (FR)</p>	 <p>B : 6 / C : 72 pcs.</p>	<p>A14ZS17E1 10297341 MG ZS (2017) Shock Absorber Bumper (RE)</p>	 <p>B : 6 / C : 72 pcs.</p>
<p>A14MG516F 10091669 MG5 (2016) Shock Absorber Bumper (FR)</p>	 <p>B : 8 / C : 96 pcs.</p>	<p>A14M516E1 10091675 MG5 (2016) Shock Absorber Bumper (RE)</p>	 <p>B : 6 / C : 72 pcs.</p>
<p>A14ZS17F1 10415595 MG ZS (2017) Shock Absorber Bumper (FR)</p>	 <p>B : 6 / C : 72 pcs.</p>		
<p>A14M614F0 10012694 MG6 (2014) Shock Dust Cover (FR)</p>	 <p>B : 2 / C : 40 pcs.</p>	<p>A14M614E0 10004502, 30019970 MG6 (2014) Shock Dust Cover (RE)</p>	 <p>B : 2 / C : 40 pcs.</p>
<p>A14M614F1 30048330 MG6 (2014) Shock Absorber Bumper (FR)</p>	 <p>B : 6 / C : 72 pcs.</p>		
<p>A14HS19E0 10525151, 10525152 MG HS (2019) Shock Dust Cover (RE)</p>	<p>NEW</p>  <p>B : 2 / C : 12 pcs.</p>	<p>A14M314E1 10039881 MG3 (2014) Shock Absorber Bumper (RE)</p>	<p>NEW</p>  <p>B : 6 / C : 72 pcs.</p>
<p>A21M617F 30000157 MG6 (2014) Stabilizer Shaft Rubber (FR)</p>	 <p>B : 8 / C : 192 pcs.</p>	<p>A21M617E 10051910 MG6 (2014) Stabilizer Shaft Rubber (RE)</p>	 <p>B : 8 / C : 192 pcs.</p>
<p>A21M516F 50016118 MG5 (2016) Stabilizer Shaft Rubber (FR)</p>	<p>NEW</p>  <p>B : 12 / C : 288 pcs.</p>	<p>A21ZS17F 10227886 MG ZS (2017) Stabilizer Shaft Rubber (FR)</p>	<p>NEW</p>  <p>B : 16 / C : 384 pcs.</p>



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

MG






<p>A24HS19WB 10180037-0, 10180038-0 MG HS (2019) Lower Arm Bushing (BIG LH,RH)</p>	 <p>B : 4 / C : 72 pcs.</p>	<p>A24HS19WS 10094236 MG HS (2019) Lower Arm Bushing (SMALL)</p>	 <p>B : 6 / C : 108 pcs.</p>
<p>A24ZS17WB 10228170, 10252196-1 MG ZS (2017) Lower Arm Bushing (BIG)</p>	 <p>B : 4 / C : 72 pcs.</p>	<p>A24ZS17WS 10228160, 10252196-2 MG ZS (2017) Lower Arm Bushing (SMALL)</p>	 <p>B : 6 / C : 108 pcs.</p>
<p>A24M614WB 30020135, 30020136, 30020138 MG6 (2014) Lower Arm Bushing (LH, RH BIG)</p>	 <p>B : 4 / C : 72 pcs.</p>	NEW	
<p>A25HS1916 10094116 MG HS (2019) Suspension Bush (RE)</p>	 <p>B : 10 / C : 180 pcs.</p>	<p>A25HS1926 10094126 MG HS (2019) Suspension Bush (RE)</p>	 <p>B : 6 / C : 108 pcs.</p>
<p>A25HS1969 10141769 MG HS (2019) Suspension Bush (RE)</p>	 <p>B : 10 / C : 180 pcs.</p>	<p>A25HS1990 10094090 MG HS (2019) Suspension Bush (RE)</p>	 <p>B : 10 / C : 180 pcs.</p>
<p>A25M614PT 30000167 MG6 (2014) Suspension Bush (RE)</p>	 <p>B : 10 / C : 180 pcs.</p>		
<p>A25M614PG 30000171 MG6 (2014) Suspension Bush (RE UP, LONG)</p>	 <p>B : 10 / C : 180 pcs.</p>	<p>A25M61433 30022933 MG6 (2014) Suspension Bush (RE, SMALL)</p>	 <p>B : 6 / C : 108 pcs.</p>



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

MG

<p>A27MG614E</p> <p>30000192</p> <p>MG6 (2014)</p> <p>Link Assy (RE)</p>	 <p>B : 2 / C : 54 pcs.</p>
<p>A27MG516F</p> <p>10091671</p> <p>MG5 (2016)</p> <p>Link Assy (FR)</p>	 <p>B : 2 / C : 40 pcs.</p>
<p>A27ZS17F</p> <p>10227851</p> <p>MG ZS (2017)</p> <p>Link Assy (FR)</p>	 <p>B : 2 / C : 32 pcs.</p>
<p>A27HS19E</p> <p>10094355</p> <p>MG HS (2019)</p> <p>Link Assy (RE)</p>	<p>NEW</p>  <p>B : 2 / C : 108 pcs.</p>
<p>A27M314F</p> <p>30003601</p> <p>MG3 (2014)</p> <p>Link Assy (FR)</p>	<p>NEW</p>  <p>B : 2 / C : 32 pcs.</p>



MISCELLANEOUS PARTS

<p>X19001 XX002 J13, 720 Diaphragm</p>		<p>B : 1 / C : 48 pcs.</p>	<p>X19002 2500877 J15, 620 Diaphragm</p>		<p>B : 1 / C : 48 pcs.</p>
<p>X19003 VH440-10 PBR Diaphragm (BIG)</p>		<p>B : 1 / C : 48 pcs.</p>	<p>X19004 VH44-30 PBR Diaphragm (SMALL)</p>		<p>B : 1 / C : 48 pcs.</p>
<p>X19005 56112-09408 D/S Shock Absorber Rubber</p>		<p>B : 100 / C : 2,400 pcs.</p>	<p>X19006 56112-94000 D/S, S250, GR03 Shock Absorber Rubber (UPPER, BIG)</p>		<p>B : 100 / C : 1,600 pcs.</p>
<p>X19007 56112-09400 D/S (GR01) Shock Absorber Rubber (SMALL)</p>		<p>B : 100 / C : 2,400 pcs.</p>	<p>X19008 56119-32201 JEEP TAPER (GR02) Shock Absorber Rubber</p>		<p>B : 100 / C : 1,600 pcs.</p>
<p>X19010 8-94226577-3 JEEP, KBZ, L200 Shock Absorber Rubber</p>		<p>B : 50 / C : 800 pcs.</p>	<p>X19012 35-30-15 GR82 Shock Absorber Rubber</p>		<p>B : 50 / C : 800 pcs.</p>
<p>X19013 8-97236303-0 D-MAX (2002, 2008) (2WD), (2012) RT50 (2WD, 4WD) VIGO (2WD, 4WD) Shock Absorber Rubber</p>		<p>B : 30 / C : 720 pcs.</p>	<p>X19014 13500-13510 KM, KT925 Shock Absorber Rubber</p>		<p>B : 20 / C : 320 pcs.</p>
<p>X19016 18-32-28 GR208 Shock Absorber Rubber</p>		<p>B : 80 / C : 1,280 pcs.</p>	<p>X19017 8-94235319-0 BUS (260 HP) Shock Absorber Rubber</p>		<p>B : 12 / C : 192 pcs.</p>
<p>X19018 9-37518030-0 KT725 Shock Absorber Rubber</p>		<p>B : 36 / C : 576 pcs.</p>	<p>X19019 10301-90201 TX Shock Absorber Rubber</p>		<p>B : 28 / C : 672 pcs.</p>



MISCELLANEOUS PARTS

<p>X19024 182332279 RBI Dust Cover (SMALL)</p>  <p>B : 32 / C : 768 pcs.</p>	<p>X19025 182332255 RBI Dust Cover (MIDDLE)</p>  <p>B : 25 / C : 400 pcs.</p>
<p>X19026 182332266 RBI Dust Cover (BIG)</p>  <p>B : 20 / C : 320 pcs.</p>	<p>X19029 182332244 RBI Dust Cover (MIDDLE)</p>  <p>B : 32 / C : 768 pcs.</p>
<p>X28000 XX280 RBI Bumper Bound</p>  <p>B : 10 / C : 120 pcs.</p>	<p>X19023 107 92 00 82 BENZ Exhaust Pipe Support</p>  <p>B : 20 / C : 480 pcs.</p>
<p>X28001 XX281 RBI Bumper Bound (LOW)</p>  <p>B : 6 / C : 72 pcs.</p>	<p>X28002 XX282 RBI Bumper Bound (HIGH)</p>  <p>B : 4 / C : 48 pcs.</p>
<p>L2201 L2201 LAND800, 900 Shock Absorber Rubber</p>  <p>B : 36 / C : 576 pcs.</p>	<p>L2202 90385-T0004, 19007 LAND S250, VIGO (2WD, 4WD), INNOVA (2004) (KUN40), FORTUNER (2005) Shock Absorber Rubber</p>  <p>B : 50 / C : 800 pcs.</p>



MISCELLANEOUS PARTS

<p>X26001 47856-10021 BIG-M, 720, TFR Shock Absorber Bush</p>	 B : 24 / C : 384 pcs.	<p>X19015 XX1091 RBI (15 mm) Water Pump Cap</p>	 B : 50 / C : 800 pcs.
<p>X19009 RB1020 RBI Bumper Bound</p>	 B : 50 / C : 800 pcs.		
<p>X19021 XX193 THICK Suspension Rubber</p>	 B : 12 / C : 288 pcs.	<p>X19022 XX194 THIN Suspension Rubber</p>	 B : 18 / C : 432 pcs.
<p>X31001 17572-74021 RBI (8 mm) Exhaust Pipe Support</p>	 B : 20 / C : 320 pcs.	<p>X10KU001 52200-25160 KUBOTA Front Engine Mounting</p>	 B : 4 / C : 48 pcs.
<p>X30231 55100-60810 VITARA Cylinder Piston</p>	 B : 1 / C : 60 pcs.	<p>X30232 55100-60830 SWIFT Cylinder Piston</p>	 B : 1 / C : 60 pcs.
<p>X30233 87731-87706 APPLAUSE Cylinder Piston</p>	 B : 1 / C : 60 pcs.		
<p>Y2401SW 661 333 3114 SSANGYONG Lower Arm Bushing</p>	 B : 6 / C : 108 pcs.		
<p>124CP1W KD101 34 460 FESTIVA, ASPIRE Lower Arm Bushing</p>	 B : 10 / C : 180 pcs.	<p>127F01E 2M51 5E 494AB FORD FOCUS Stabilizer Link</p>	 B : 10 / C : 120 pcs.