

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**













ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

**MAZDA**

<p>D0936E</p> <p>BR74 39 040</p> <p>323 SEDAN (1992)</p> <p>Front Engine Bushing (RE)</p>  <p>B : 4 / C : 48 pcs.</p>	<p>D0936EZ</p> <p>BR74 39 040-IN</p> <p>323 SEDAN (1992)</p> <p>Insulator Engine (RE)</p>  <p>B : 2 / C : 24 pcs.</p>
<p>D0936F</p> <p>B455 39 050B</p> <p>323 SEDAN (1992)</p> <p>Front Engine Bushing (FR)</p>  <p>B : 4 / C : 48 pcs.</p>	<p>D0936FZ</p> <p>B455 39 050B-IN</p> <p>323 SEDAN (1992)</p> <p>Insulator Engine (FR)</p>  <p>B : 2 / C : 24 pcs.</p>
<p>D0936L</p> <p>B455 39 100E</p> <p>323 SEDAN (1992)</p> <p>Front Engine Bushing (LH)</p>  <p>B : 4 / C : 48 pcs.</p>	
<p>D0936R</p> <p>B455 39 060E</p> <p>323 SEDAN (1992)</p> <p>Front Engine Bushing (RH)</p>  <p>B : 2 / C : 24 pcs.</p>	<p>D0936RZ</p> <p>B455 39 060E-IN</p> <p>323 SEDAN (1992)</p> <p>Insulator Engine (RH)</p>  <p>B : 1 / C : 12 pcs.</p>
<p>D0937EA</p> <p>BC1D 39 040B</p> <p>323 SEDAN (1995)</p> <p>Front Engine Bushing (RE, A/T)</p>  <p>B : 4 / C : 48 pcs.</p>	
<p>D0937FA</p> <p>BC1G 39 050B</p> <p>323 SEDAN (1995)</p> <p>Front Engine Bushing (FR, A/T)</p>  <p>B : 2 / C : 24 pcs.</p>	<p>D0937FAZ</p> <p>BC1G 39 050B-IN</p> <p>323 SEDAN (1995)</p> <p>Insulator Engine (FR, A/T)</p>  <p>B : 2 / C : 24 pcs.</p>
<p>D0937FM</p> <p>BC1D 39 050A</p> <p>323 SEDAN (1995)</p> <p>Front Engine Bushing (FR, M/T)</p>  <p>B : 4 / C : 48 pcs.</p>	
<p>D0937LA</p> <p>BC1E 39 100C, BC1D 39 100E</p> <p>323 SEDAN (1995)</p> <p>Front Engine Bushing (LH, A/T, M/T)</p>  <p>B : 4 / C : 48 pcs.</p>	





**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,  
KLONGTOEI, BANGKOK 10110 THAILAND  
TEL: (66) 2 392 1148  
E-MAIL: rbiautoparts@gmail.com

**MAZDA**

<p>D0964EA</p> <p>GA2C 39 040E</p> <p>CRONOS</p> <p>Front Engine Bushing (RE, A/T)</p>  <p>B : 2 / C : 24 pcs.</p>	<p>D0964EAZ</p> <p>GA2C 39 040E-IN</p> <p>CRONOS</p> <p>Insulator Engine (RE, A/T)</p>  <p>B : 1 / C : 8 pcs.</p>
<p>D0964EM</p> <p>GA2A 39 040A</p> <p>CRONOS</p> <p>Front Engine Bushing (RE, M/T)</p>  <p>B : 2 / C : 24 pcs.</p>	<p>D0964EMZ</p> <p>GA2A 39 040A-IN</p> <p>CRONOS</p> <p>Insulator Engine (RE, M/T)</p>  <p>B : 1 / C : 12 pcs.</p>
<p>D0964FA</p> <p>GA2C 39 050</p> <p>CRONOS</p> <p>Front Engine Bushing (FR, A/T)</p>  <p>B : 4 / C : 48 pcs.</p>	<p>D0964FAZ</p> <p>GA2C 39 050-IN</p> <p>CRONOS</p> <p>Insulator Engine (FR, A/T)</p>  <p>B : 2 / C : 24 pcs.</p>
<p>D0964FM</p> <p>GA2A 39 050</p> <p>CRONOS</p> <p>Front Engine Bushing (FR, M/T)</p>  <p>B : 4 / C : 48 pcs.</p>	<p>D0964FMZ</p> <p>GA2A 39 050-IN</p> <p>CRONOS</p> <p>Insulator Engine (FR, M/T)</p>  <p>B : 2 / C : 24 pcs.</p>
<p>D0964LA</p> <p>GE6T 39 070A</p> <p>CRONOS</p> <p>Front Engine Bushing (LH, A/T)</p>  <p>B : 4 / C : 48 pcs.</p>	<p>D0964LAZ</p> <p>GE6T 39 070A-IN</p> <p>CRONOS</p> <p>Insulator Engine (LH, A/T)</p>  <p>B : 1 / C : 8 pcs.</p>
<p>D0964LM</p> <p>GE4T 39 070A</p> <p>CRONOS</p> <p>Front Engine Bushing (LH, M/T)</p>  <p>B : 4 / C : 48 pcs.</p>	
<p>D09A00F</p> <p>B25D 39 050C</p> <p>323 SEDAN (2000) PROTEGE</p> <p>Front Engine Bushing (FR)</p>  <p>B : 4 / C : 48 pcs.</p>	<p>D09A00FZ</p> <p>B25D 39 050C-IN</p> <p>323 SEDAN (2000)</p> <p>Insulator Engine (FR)</p>  <p>B : 2 / C : 24 pcs.</p>
<p>D09A00LM</p> <p>B25D, B25E 39 070C</p> <p>323 SEDAN (2000) PROTEGE</p> <p>Front Engine Bushing (LH, M/T, A/T)</p>  <p>B : 4 / C : 48 pcs.</p>	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

**MAZDA**

<p><b>D09A00RB</b></p> <p>BJ0N 39 06YD</p> <p>323 SEDAN (2000) PROTEGE (1.8 cc)</p> <p>Front Engine Bushing (RH, BIG)</p>		<p>B : 2 / C : 24 pcs.</p>	
<p><b>D09A00RS</b></p> <p>B25D 39 06YC</p> <p>323 SEDAN (2000) PROTEGE (1.6 cc)</p> <p>Front Engine Bushing (RH, SMALL)</p>		<p>B : 4 / C : 48 pcs.</p>	
<p><b>D09A00E</b></p> <p>BJ0N 39 040C, B25D 39 040</p> <p>323 SEDAN (2000) PROTEGE</p> <p>Front Engine Bushing (RE)</p>		<p>B : 4 / C : 48 pcs.</p>	





**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**  
 ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,  
 KLONGTOEI, BANGKOK 10110 THAILAND  
 TEL: (66) 2 392 1148  
 E-MAIL: rbiautoparts@gmail.com

# MAZDA

<p>D10010 0370 39 040A 808 Front Engine Mounting</p>  <p>B : 6 / C : 72 pcs.</p>	
<p>D1042L 0317 39 050 M1300, M1400 Front Engine Mounting (LH)</p>  <p>B : 1 / C : 12 pcs.</p>	<p>D1042R 0317 39 040 M1300, M1400 Front Engine Mounting (RH)</p>  <p>B : 1 / C : 12 pcs.</p>
<p>D1043L 0223 39 090 M1600 Front Engine Mounting (LH)</p>  <p>B : 1 / C : 6 pcs.</p>	<p>D1043R 0223 39 060 M1600 Front Engine Mounting (RH)</p>  <p>B : 1 / C : 6 pcs.</p>
<p>D10450 UB39 39 040A MAGNUM, FIGHTER Front Engine Mounting</p>  <p>B : 2 / C : 24 pcs.</p>	
<p>D1062E G030 39 040 626 GLX Front Engine Mounting (RE)</p>  <p>B : 1 / C : 12 pcs.</p>	<p>D1062F GC76 39 050A 626 GLX Front Engine Mounting (FR)</p>  <p>B : 1 / C : 6 pcs.</p>
<p>D10E200LR S083 39 040B, S113 39 040B E2000, E2200 (1987-1997) Front Engine Mounting (LH, RH)</p>  <p>B : 2 / C : 24 pcs.</p>	

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**








ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

**MAZDA**

<p><b>D11410</b></p> <p>0259 39 340, 0437 39 340A M1200, M1300, M1600, MAGNUM, FIGHTER</p> <p>Rear Engine Mounting</p>  <p>B : 2 / C : 24 pcs.</p>	
<p><b>D1164A</b></p> <p>GA2G 39 100</p> <p>CRONOS</p> <p>Rear Engine Mounting (A/T)</p>  <p>B : 2 / C : 24 pcs.</p>	<p><b>D1164M</b></p> <p>GA2E 39 100A</p> <p>CRONOS</p> <p>Rear Engine Mounting (M/T)</p>  <p>B : 2 / C : 24 pcs.</p>
<p><b>D112XM</b></p> <p>UH71 39 340</p> <p>FIGHTER, RANGER (2WD)</p> <p>Rear Engine Mounting (M/T)</p>  <p>B : 2 / C : 24 pcs.</p>	<p><b>D112XA</b></p> <p>UH72 39 340</p> <p>FIGHTER, RANGER (2WD)</p> <p>Rear Engine Mounting (A/T)</p>  <p>B : 2 / C : 24 pcs.</p>
<p><b>D114XB</b></p> <p>UH74 39 34X</p> <p>FIGHTER, RANGER (4WD)</p> <p>Rear Engine Mounting (BIG)</p>  <p>B : 2 / C : 24 pcs.</p>	<p><b>D114XS</b></p> <p>UH74 39 33X</p> <p>FIGHTER, RANGER (4WD)</p> <p>Rear Engine Mounting (SMALL)</p>  <p>B : 4 / C : 48 pcs.</p>





**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**  
 ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,  
 KLONGTOEI, BANGKOK 10110 THAILAND  
 TEL: (66) 2 392 1148  
 E-MAIL: rbiautoparts@gmail.com

# MAZDA

\* RBI Shock Absorber Mounting is assembled with Japanese Bearing

<p>D1333E</p> <p>B001 28 390</p> <p>323 XG</p> <p>Shock Absorber Mounting (RE)</p> <p>B : 1 / C : 20 pcs.</p> 	
<p>D1333F</p> <p>B001 34 390C</p> <p>323 XG</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 	<p>D1335F</p> <p>B481 34 380C</p> <p>323 ASTINA</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 16 pcs.</p> 
<p>D1336F</p> <p>B455 34 380D</p> <p>323 SEDAN (1992)</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 	<p>D1338F</p> <p>B01C 34 380</p> <p>323 SEDAN (1995)</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 
<p>D1361F</p> <p>8173 34 380A</p> <p>626 GLX</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 	<p>D1362F</p> <p>G030 34 390E</p> <p>626 GLX</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 
<p>D1362EL</p> <p>G030 28 390</p> <p>626 GLX</p> <p>Shock Absorber Mounting (RE, LH)</p> <p>B : 1 / C : 20 pcs.</p> 	<p>D1362ER</p> <p>G030 28 380</p> <p>626 GLX</p> <p>Shock Absorber Mounting (RE, RH)</p> <p>B : 1 / C : 20 pcs.</p> 
<p>D1364F</p> <p>GA5R 34 380</p> <p>CRONOS</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 	<p>D13A00F</p> <p>CB01 34 380B</p> <p>323 SEDAN (2000)</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 
<p>D13T20F</p> <p>E112 34 390C, E112 34 380D</p> <p>TRIBUTE, ESCAPE</p> <p>Shock Absorber Mounting (FR)</p> <p>B : 1 / C : 20 pcs.</p> 	
<p>D13T200</p> <p>E112 28 775</p> <p>TRIBUTE, ESCAPE</p> <p>Shock Absorber Rubber</p> <p>B : 24 / C : 1,560 pcs.</p> 	





**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**  
 ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,  
 KLONGTOEI, BANGKOK 10110 THAILAND  
 TEL: (66) 2 392 1148  
 E-MAIL: rbiautoparts@gmail.com

# MAZDA

\* RBI Shock Absorber Mounting is assembled with Japanese Bearing

<p>D13MZ3F BP4L 34 380 MAZDA3 Shock Absorber Mounting (FR)</p>  <p>B : 1 / C : 20 pcs.</p>	<p>D13MZ3E BP4L 28 390 MAZDA3 Shock Absorber Mounting (RE)</p>  <p>B : 10 / C : 200 pcs.</p>
<p>D13MZ2F D651 34 380B MAZDA2 (2007) DE, FIESTA, ECOSPORT Shock Absorber Mounting (FR)</p>  <p>B : 1 / C : 20 pcs.</p>	<p>D13MZ2E DL33 28 390 MAZDA2, FIESTA Shock Absorber Mounting (RE)</p>  <p>B : 10 / C : 200 pcs.</p>
<p>D13BT50F UC2R 34 775B BT50 PRO (2WD), (4WD) Shock Absorber Rubber</p>  <p>B : 20 / C : 400 pcs.</p>	
<p>D1338EL BC1D 28 390B SEDAN (1995) Shock Absorber Mounting (RE, LH)</p>  <p>B : 1 / C : 20 pcs.</p>	<p>D1338ER BC1D 28 380B SEDAN (1995) Shock Absorber Mounting (RE, RH)</p>  <p>B : 1 / C : 20 pcs.</p>
<p>D13CX12E KD45 28 910J-2 CX5 (2012) Shock Absorber Mounting (RE)</p>  <p>B : 10 / C : 200 pcs.</p>	<p>D13CX12F KD35 34 380C, DA6A 34 380 MAZDA3 (2013) SKYACTIV, BM, BN, MAZDA2 (2014) SKYACTIV, DJ, CX5 (2012), CX3 (2016) DK Shock Absorber Mounting (FR)</p>  <p>B : 1 / C : 20 pcs.</p>

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

**MAZDA**

<p>D1433E</p> <p>B001 28 111</p> <p>323 XG</p> <p>Shock Dust Cover (RE)</p> <p>B : 2 / C : 40 pcs.</p> 	<p>D1433F</p> <p>B001 34 111</p> <p>323 XG</p> <p>Shock Dust Cover (FR)</p> <p>B : 2 / C : 40 pcs.</p> 
<p>D1436E</p> <p>B455 28 111A</p> <p>323 SEDAN (B6)</p> <p>Shock Dust Cover (RE)</p> <p>B : 2 / C : 44 pcs.</p> 	<p>D1436F</p> <p>B455 34 111B</p> <p>323 SEDAN (B6)</p> <p>Shock Dust Cover (FR)</p> <p>B : 2 / C : 40 pcs.</p> 
<p>D14A00E1</p> <p>B01C 28 0A5A</p> <p>323 SEDAN (1995-2000)</p> <p>Shock Dust Cover (RE)</p> <p>B : 2 / C : 40 pcs.</p> 	<p>D14A00F1</p> <p>C100 34 0A5</p> <p>323 SEDAN (1995-2000)</p> <p>Shock Dust Cover (FR)</p> <p>B : 2 / C : 40 pcs.</p> 
<p>D14MZ3E0</p> <p>3N61 5K 570</p> <p>MAZDA3</p> <p>Shock Dust Cover (RE)</p> <p>B : 2 / C : 12 pcs.</p> 	<p>D14MZ3F0</p> <p>BP4K 34 0A5B</p> <p>MAZDA3</p> <p>Shock Dust Cover (FR)</p> <p>B : 2 / C : 40 pcs.</p> 
<p>D14MZ20E</p> <p>DL33 28 1A1</p> <p>MAZDA2, FIESTA</p> <p>Shock Dust Cover (RE)</p> <p>B : 4 / C : 24 pcs.</p> 	<p>D14MZ20F</p> <p>D651 34 111A</p> <p>MAZDA2 (2007) DE, FIESTA, ECOSPORT</p> <p>Shock Absorber Bumper (FR)</p> <p>B : 6 / C : 72 pcs.</p> 
<p>D14T20F1</p> <p>E112 34 0A5</p> <p>TRIBUTE, ESCAPE</p> <p>Shock Dust Cover (FR)</p> <p>B : 2 / C : 40 pcs.</p> 	<p>D14MZ200F</p> <p>DL33 34 012</p> <p>MAZDA2 (2007) DE, FIESTA, ECOSPORT</p> <p>Shock Dust Cover (FR)</p> <p>B : 1 / C : 24 pcs.</p> 
<p>D14A00E</p> <p>B25D 28 111</p> <p>323 SEDAN (2000)</p> <p>Shock Absorber Bumper (RE)</p> <p>B : 4 / C : 48 pcs.</p> 	<p>D14A00F</p> <p>C100 34 111A</p> <p>323 SEDAN (1995-2000)</p> <p>Shock Absorber Bumper (FR)</p> <p>B : 6 / C : 72 pcs.</p> 
<p>D14MZ3E</p> <p>BP4K 28 1B0A</p> <p>MAZDA3</p> <p>Shock Absorber Bumper (RE)</p> <p>B : 10 / C : 120 pcs.</p> 	<p>D14MZ3F</p> <p>BP4K 34 111B</p> <p>MAZDA3</p> <p>Shock Absorber Bumper (FR)</p> <p>B : 6 / C : 72 pcs.</p> 







**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

# MAZDA

<p><b>D14T20E</b> E112 28 1A0 TRIBUTE, ESCAPE Shock Absorber Bumper (RE) B : 4 / C : 48 pcs.</p> 	<p><b>D14T20F</b> E112 34 111B TRIBUTE, ESCAPE Shock Absorber Bumper (FR) B : 6 / C : 72 pcs.</p> 
<p><b>D14M313F0</b> BPH4 34 111A, B45A 34 111 MAZDA3 (2013) SKYACTIV, BM, BN Shock Absorber Bumper (FR) B : 6 / C : 72 pcs.</p> 	
<p><b>D14CX12E</b> KD35 28 1A0 MAZDA3 (2013) SKYACTIV, BM, BN, MAZDA2 (2014) SKYACTIV, DJ, CX5 (2012) Shock Dust Cover (RE) B : 2 / C : 12 pcs.</p> 	<p><b>D14CX12F</b> KD35 34 111 MAZDA CX5 (2012) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs.</p> 
<p><b>D14M214F0</b> DA6V 34 111 MAZDA2 (2014) SKYACTIV, DJ Shock Absorber Bumper (FR) B : 6 / C : 72 pcs.</p> 	
<p><b>D14CX17E0</b> KB7W 28 1A0 CX5 (2017) Shock Dust Cover (RE) B : 2 / C : 12 pcs.</p> 	<p><b>D14CX17F1</b> KB7W 34 111 CX5 (2017) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs.</p> 





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D1731IZ F001 22 540 323 XG Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D1731UZ F001 22 530 323 XG Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D1736IZ F024 22 540 323 SEDAN (1992) Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D1736UZ F024 22 530 323 SEDAN (1992) Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D1737IZ F061 22 540 323 SEDAN (1995), ASTINA Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D1737UZ F069 22 530A, F061 22 530B 323 SEDAN (1995), ASTINA Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D174X1IZ M080 22 540 FIGHTER, RANGER (4WD) Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D174X1UZ M080 22 530A FIGHTER, RANGER (4WD) Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D1761IZ G001 22 540 626 GLX Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D1761UZ G001 22 530 626 GLX Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D1764IZ G560 22 540 CRONOS Drive Shaft Boot (INNER, A/T)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D1764UZ G560 22 530 CRONOS Drive Shaft Boot (OUTER, A/T)</p>  <p>B : 2 / C : 100 pcs.</p>
	<p>D17A00UB FA21 22 530A 323 SEDAN (2000) (1.8 cc), PROTEGE Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
	<p>D17A00UZ FA50 22 530 323 SEDAN (2000) (1.6 cc), PROTEGE Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D17MZ21A FA81 22 540 MAZDA2, FIESTA Drive Shaft Boot (INNER, A/T)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17MZ2UA FA81 22 530A MAZDA2, FIESTA Drive Shaft Boot (OUTER, A/T)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17MZ21M FD80 22 540 MAZDA2, FIESTA Drive Shaft Boot (INNER, M/T)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17MZ2UM FD80 22 530A MAZDA2, FIESTA Drive Shaft Boot (OUTER, M/T)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17MZ310 FG02 22 540 MAZDA3 (1.6 cc) Drive Shaft Boot (INNER, A/T)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17T20IF YL8Z 3A331 AA TRIBUTE, ESCAPE Drive Shaft Boot (FR, INNER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17MZ31M FG01 22 540 MAZDA3 (1.6 cc) Drive Shaft Boot (INNER, M/T)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17MZ3UZ GG25 22 530, FG01 22 530, FG02 22 530 MAZDA3 (2003-2008) (1.6, 2.0 cc) Drive Shaft Boot (OUTER, A/T, M/T)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17MZ31Z GG25 22 540 MAZDA3 (2.0 cc) Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17T20UF GG15 22 530 TRIBUTE, ESCAPE Drive Shaft Boot (FR, OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17M3131Z FTC3 22 540 MAZDA3 (2013) SKYACTIV, BM, BN Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17M313UZ FTC3 22 530 MAZDA3 (2013) SKYACTIV, BM, BN Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17T20IZ GD29 22 540 TRIBUTE, ESCAPE Drive Shaft Boot (RE, INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17T20UE GD29 22 530 TRIBUTE, ESCAPE Drive Shaft Boot (RE, OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17M214IA FTD1 22 540, FTT1 22 540 MAZDA2 (2014) SKYACTIV, DJ (B) Drive Shaft Boot (INNER, A/T)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17M214UA FTD1 22 530, FTT1 22 530 MAZDA2 (2014) SKYACTIV, DJ (B) Drive Shaft Boot (OUTER, A/T)</p>  <p>B : 2 / C : 100 pcs.</p>





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D17CX12BFI</p> <p>GG62 22 540</p> <p>MAZDA3 (2011) BL (2.0 cc), CX5 (2012) (B)</p> <p>Drive Shaft Boot (A/T FR, INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17CX12DFU</p> <p>FTB4 22 530</p> <p>CX5 (2012) (D)</p> <p>Drive Shaft Boot (FR, OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17T231Z</p> <p>GP06 22 540</p> <p>TRIBUTE, ESCAPE (2.3 cc)</p> <p>Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17T23UZ</p> <p>GA35 22 530A</p> <p>TRIBUTE, ESCAPE (2.3 cc)</p> <p>Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17BT54I</p> <p>PP01 22 540</p> <p>BT50 (4WD)</p> <p>Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17BT54U</p> <p>PP01 22 530</p> <p>BT50 (4WD)</p> <p>Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17CX12EI</p> <p>RTA1 22 540</p> <p>CX5 (2012) (4WD)</p> <p>Drive Shaft Boot (RE, INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17CX12EU</p> <p>RTA1 22 530</p> <p>CX5 (2012) (4WD)</p> <p>Drive Shaft Boot (RE, OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17CX12DFI</p> <p>FTB4 22 540</p> <p>CX5 (2012) (D)</p> <p>Drive Shaft Boot (FR, INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17CX12FU</p> <p>GG62 22 530</p> <p>MAZDA3 (2011) BL (2.0 cc), CX5 (2012) (B)</p> <p>Drive Shaft Boot (A/T FR, OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p>D17BT50IZ</p> <p>UCY2 22 540, UCY3 22 540</p> <p>BT50 PRO (2012,2015)</p> <p>Drive shaft boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p>D17BT50UZ</p> <p>UCY2 22 530, UCY3 22 530</p> <p>BT50 PRO (2012,2015)</p> <p>Drive shaft boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts











## MAZDA

<p>D1831LZ B001 32 118 323 XG Steering Gear Boot (LH)      B : 2 / C : 50 pcs.</p> 	<p>D1831RZ B001 32 125 323 XG Steering Gear Boot (RH)      B : 2 / C : 50 pcs.</p> 
<p>D1836PZ B456 32 125 323 SEDAN Steering Gear Boot (POWER)      B : 2 / C : 50 pcs.</p> 	<p>D1861Z G030 32 125 626 XG Steering Gear Boot (LH, RH)      B : 2 / C : 50 pcs.</p> 
<p>D1862PZ H002 32 125 GLX Steering Gear Boot (POWER)      B : 2 / C : 50 pcs.</p> 	<p>D18640 GA2A 32 125 CRONOS Steering Gear Boot      B : 2 / C : 50 pcs.</p> 
<p>D18A000 GJ25 32 125 PROTEGE, 626 TTL Steering Gear Boot      B : 2 / C : 50 pcs.</p> 	<p>D18MZ30Z BP4L 32 12XM00 MAZDA3 Steering Gear Boot      B : 2 / C : 50 pcs.</p> 
<p>D18T20Z E112 32 F0Y TRIBUTE, ESCAPE Steering Gear Boot      B : 2 / C : 50 pcs.</p> 	<p>D18MZ20Z D651 32 12X MAZDA2, FIESTA Steering Gear Boot      B : 2 / C : 50 pcs.</p> 
<p>D19BT5017 U6A1 25 18X BT50 PRO Steering Gear Boot      B : 2 / C : 32 pcs.</p> 	





## MAZDA

<p><b>D2001B</b> 0866 28 333B 808 Spring Shackle Rubber (BIG, FR)</p>  <p>B : 20 / C : 480 pcs.</p>	<p><b>D2001G</b> 0866 28 353B 808 Spring Shackle Rubber (LONG, FR)</p>  <p>B : 28 / C : 672 pcs.</p>
<p><b>D2001T</b> 0866 28 343B 808 Spring Shackle Rubber (SHORT, RE)</p>  <p>B : 36 / C : 864 pcs.</p>	
<p><b>D2002B</b> 0443 28 333 929 Spring Shackle Rubber (BIG)</p>  <p>B : 12 / C : 288 pcs.</p>	<p><b>D2002G</b> 1011 28 353 929 Spring Shackle Rubber (LONG, RE)</p>  <p>B : 20 / C : 320 pcs.</p>
<p><b>D2002T</b> 0443 28 343 929, M1200, M1400 Spring Shackle Rubber (SHORT, RE)</p>  <p>B : 20 / C : 480 pcs.</p>	
<p><b>D2045T</b> UB40 28 333, UH71 28 480 MAGNUM, FIGHTER, BT50 Spring Shackle Rubber (SHORT, RE)</p>  <p>B : 20 / C : 480 pcs.</p>	<p><b>D2045G</b> UB39 28 333, UH71 28 470 MAGNUM, FIGHTER, BT50 Spring Shackle Rubber (LONG, RE)</p>  <p>B : 16 / C : 384 pcs.</p>
<p><b>D20BT500ET</b> UC2R 28 480B BT50 PRO, RANGER (2012) Spring Shackle Rubber (RE)</p>  <p>B : 16 / C : 384 pcs.</p>	<p><b>D20BT501EG</b> UC2R 28 470B BT50 PRO, RANGER (2012) Spring Shackle Rubber (RE)</p>  <p>B : 8 / C : 192 pcs.</p>





## MAZDA

<p>D21010</p> <p>34 156</p> <p>808</p> <p>Stabilizer Shaft Rubber (SMALL Diameter)</p> <p>B : 5 / C : 120 pcs.</p> 	<p>D21020</p> <p>0305 34 156</p> <p>929</p> <p>Stabilizer Shaft Rubber (BIG Diameter)</p> <p>B : 5 / C : 120 pcs.</p> 
<p>D21330</p> <p>B029 34 156A</p> <p>XG, 323 XL</p> <p>Stabilizer Shaft Rubber</p> <p>B : 14 / C : 336 pcs.</p> 	
<p>D2136E</p> <p>B457 28 156A</p> <p>SEDAN (1992)</p> <p>Stabilizer Shaft Rubber (RE)</p> <p>B : 20 / C : 480 pcs.</p> 	<p>D2136F</p> <p>B459 34 156A</p> <p>SEDAN (1992)</p> <p>Stabilizer Shaft Rubber (FR)</p> <p>B : 20 / C : 480 pcs.</p> 
<p>D2137F</p> <p>BC1D 34 156</p> <p>SEDAN (1995)</p> <p>Stabilizer Shaft Rubber (FR)</p> <p>B : 20 / C : 480 pcs.</p> 	<p>D2137E</p> <p>G564 28 156A</p> <p>SEDAN (1995-2000)</p> <p>Stabilizer Shaft Rubber (RE)</p> <p>B : 20 / C : 480 pcs.</p> 
<p>D21430</p> <p>0603 34 156</p> <p>B1600</p> <p>Stabilizer Shaft Rubber</p> <p>B : 20 / C : 480 pcs.</p> 	<p>D21440</p> <p>UA01 34 156</p> <p>B2200</p> <p>Stabilizer Shaft Rubber</p> <p>B : 20 / C : 480 pcs.</p> 
<p>D21450</p> <p>UB71 34 156A</p> <p>MAGNUM, FIGHTER, BT50</p> <p>Stabilizer Shaft Rubber (FR)</p> <p>B : 16 / C : 384 pcs.</p> 	<p>D214X1F</p> <p>UH74 34 156</p> <p>FIGHTER (4WD)</p> <p>Stabilizer Shaft Rubber (FR)</p> <p>B : 12 / C : 288 pcs.</p> 
<p>D2162E</p> <p>G067 28 156</p> <p>GLX</p> <p>Stabilizer Shaft Rubber (RE)</p> <p>B : 20 / C : 480 pcs.</p> 	<p>D2162F</p> <p>G041 34 156B</p> <p>GLX</p> <p>Stabilizer Shaft Rubber (FR)</p> <p>B : 20 / C : 480 pcs.</p> 
<p>D2164F</p> <p>GA2B 34 156</p> <p>CRONOS</p> <p>Stabilizer Shaft Rubber (FR)</p> <p>B : 12 / C : 288 pcs.</p> 	<p>D2164E</p> <p>GA2A 28 156</p> <p>CRONOS</p> <p>Stabilizer Shaft Rubber (RE)</p> <p>B : 20 / C : 480 pcs.</p> 





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA












<p><b>D21A00F</b> B26R 34 156 323 SEDAN (2.0 cc), PROTEGE Stabilizer Shaft Rubber (FR) B : 20 / C : 480 pcs.</p> 	<p><b>D21F14F</b> 1410 34 156 M1400 Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs.</p> 
<p><b>D21E200F</b> S083 34 156 E2000, E2200 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.</p> 	<p><b>D21CX122E</b> KD31 28 156D, B45A 28 156 MAZDA3 (2013) SKYACTIV, BM, BN, CX5 (2012), (2017) KF, CX8 (2020), KG (2WD) Stabilizer Shaft Rubber (RE) B : 12 / C : 288 pcs.</p> 
<p><b>D21MZ3E</b> BP4K 28 156D MAZDA3 Stabilizer Shaft Rubber (RE) B : 8 / C : 128 pcs.</p> 	<p><b>D21MZ3F</b> BP4K 34 156A MAZDA3 Stabilizer Shaft Rubber (FR) B : 8 / C : 128 pcs.</p> 
<p><b>D21BT52E</b> UR58 28 156A BT50 (2WD) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs.</p> 	<p><b>D21BT52F</b> UR58 34 156 BT50 (2WD) Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.</p> 
<p><b>D21BT54E</b> UR61 28 156B BT50 (4WD) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs.</p> 	<p><b>D21BT54F</b> UP20 34 156 BT50 (4WD) Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.</p> 
<p><b>D21MZ02F</b> DL33 34 156 MAZDA2 (2007-2011) DE, FIESTA (4D) Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs.</p> 	<p><b>D21MZ02F1</b> CN155484AA, CN1Z5484B, DN21 34 156A MAZDA2 (2012) DE, (4D, 5D SPORT), ECOSPORT Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs.</p> 
<p><b>D21MZ6F</b> GJ6A 34 156 MAZDA6 (2002-2006) Stabilizer Shaft Rubber (FR) B : 6 / C : 144 pcs.</p> 	<p><b>D21A01F</b> B03E 34 156 MAZDA 323 (1998-2002) Stabilizer Shaft Rubber (FR) B : 20 / C : 480 pcs.</p> 
<p><b>D21MZ30F</b> B37F 34 156B MAZDA3 (2003-2006) Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.</p> 	<p><b>D21MZ30E</b> B34S 28 156A MAZDA3 (2003-2006) Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs.</p> 







### MAZDA

<p><b>D21MZ60E</b> GS1D 28 156 MAZDA6 (2007) Stabilizer Shaft Rubber (RE)</p>  <p>B : 16 / C : 384 pcs.</p>	<p><b>D21MZ6E</b> GJ6A 28 156 MAZDA6 (2002-2006) Stabilizer Shaft Rubber (RE)</p>  <p>B : 16 / C : 384 pcs.</p>
<p><b>D21BT504F</b> UC3C 34 156A BT50 PRO, RANGER (2012) (2WD), (4WD) Stabilizer Shaft Rubber (FR)</p>  <p>B : 8 / C : 128 pcs.</p>	
<p><b>D21M313F</b> KD61 34 156F MAZDA3 (2013) SKYACTIV, BM, BN, MAZDA2 (2014) SKYACTIV, DJ, CX3 (2016), CX5 (2017) Stabilizer Shaft Rubber (FR)</p>  <p>B : 8 / C : 192 pcs.</p>	<p><u>Substitute Number</u></p> <ul style="list-style-type: none"> <li>- DL8W 34 156, B60P 34 156</li> <li>- GMD9 34 156</li> </ul>
<p><b>D21CX12F0</b> KD35 34 156E, D10A 34 156 CX5 (2012), MAZDA2 (2014) SKYACTIV, DJ Stabilizer Shaft Rubber (FR)</p>  <p>B : 8 / C : 192 pcs.</p>	<p><b>D21CX124E</b> KD35 28 156D MAZDA CX5 (2012) (4WD) Stabilizer Shaft Rubber (RE)</p>  <p>B : 12 / C : 288 pcs.</p>
<p><b>D2301Y</b> 1393 34 156 808, 929 Strut Bar Rubber</p>  <p>B : 24 / C : 576 pcs.</p>	<p><b>D2333Y</b> 8565 34 153 323 XG Strut Bar Rubber</p>  <p>B : 14 / C : 336 pcs.</p>
<p><b>D2345Y</b> UB39 34 136 MAGNUM, FIGHTER Strut Bar Rubber</p>  <p>B : 12 / C : 288 pcs.</p>	<p><b>D2345Z</b> UB39 34 136-S MAGNUM, FIGHTER Strut Bar Rubber (SET)</p>  <p>B : 1 / C : 65 pcs.</p>
<p><b>D23E200Y</b> S083 34 136A E2000, E2200 (1987-1997) Strut Bar Rubber</p>  <p>B : 8 / C : 192 pcs.</p>	





## MAZDA

<p>D2401W</p> <p>0866 34 460</p> <p>808, 929</p> <p>Lower Arm Bushing</p>	 <p>B : 10 / C : 180 pcs.</p>	<p>D2402W</p> <p>H001 34 460</p> <p>929</p> <p>Lower Arm Bushing</p>	 <p>B : 10 / C : 180 pcs.</p>
<p>D2412W</p> <p>0259 34 460</p> <p>M1200</p> <p>Lower Arm Bushing (SMALL Diameter)</p>	 <p>B : 10 / C : 180 pcs.</p>	<p>D2413W</p> <p>0317 34 460</p> <p>M1300</p> <p>Lower Arm Bushing (BIG Diameter)</p>	 <p>B : 10 / C : 180 pcs.</p>
<p>D2433WB</p> <p>B001 34 460, B029 34 460</p> <p>323 XG, 323 GLX</p> <p>Lower Arm Bushing (BIG)</p>	 <p>B : 8 / C : 144 pcs.</p>	<p>D2433WS</p> <p>B001 34 470</p> <p>323 XG</p> <p>Lower Arm Bushing (SMALL)</p>	 <p>B : 10 / C : 180 pcs.</p>
<p>D2437B</p> <p>B455 34 46YA</p> <p>323 SEDAN (1992)</p> <p>Lower Arm Bushing (BIG)</p>	 <p>B : 8 / C : 144 pcs.</p>	<p>D2437S</p> <p>B459 34 460, 470</p> <p>323 SEDAN (1992)</p> <p>Lower Arm Bushing (SMALL)</p>	 <p>B : 8 / C : 144 pcs.</p>
<p>D2438WB</p> <p>BC1F 34 46Y, 46YA</p> <p>323 SEDAN (1995)</p> <p>Lower Arm Bushing (BIG)</p>	 <p>B : 8 / C : 144 pcs.</p>	<p>D2438WS</p> <p>BC1D 34 470</p> <p>323 SEDAN (1995)</p> <p>Lower Arm Bushing (SMALL)</p>	 <p>B : 8 / C : 144 pcs.</p>
<p>D2432WS</p> <p>B210 34 470</p> <p>323 GLX</p> <p>Lower Arm Bushing (SMALL)</p>	 <p>B : 10 / C : 180 pcs.</p>	<p>D2441W</p> <p>0662 34 460</p> <p>M1200, M1300, M1400</p> <p>Lower Arm Bushing</p>	 <p>B : 10 / C : 180 pcs.</p>
<p>D2441XP</p> <p>UH71 34 470</p> <p>FIGHTER, RANGER (2WD), (4WD)</p> <p>Upper Arm Bushing</p>	 <p>B : 8 / C : 144 pcs.</p>	<p>D2441XW</p> <p>UH74 34 450</p> <p>FIGHTER, RANGER (4WD)</p> <p>Lower Arm Bushing</p>	 <p>B : 8 / C : 144 pcs.</p>
<p>D2443W</p> <p>1243 34 460</p> <p>M1600, B1600</p> <p>Lower Arm Bushing</p>	 <p>B : 6 / C : 108 pcs.</p>	<p>D2444W</p> <p>UA01 34 820</p> <p>B2200</p> <p>Lower Arm Bushing</p>	 <p>B : 6 / C : 108 pcs.</p>





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D2445W</p> <p>UB39 34 460</p> <p>MAGNUM, FIGHTER</p> <p>Lower Arm Bushing</p>  <p>B : 6 / C : 108 pcs.</p>	<p>D2462W</p> <p>G030 34 460D, 470D</p> <p>GLX</p> <p>Lower Arm Bushing</p>  <p>B : 8 / C : 144 pcs.</p>
<p>D2463WB</p> <p>GJ21 34 460B</p> <p>626 TTL</p> <p>Lower Arm Bushing (BIG)</p>  <p>B : 6 / C : 108 pcs.</p>	<p>D2463WS</p> <p>KA10 34 470A</p> <p>626 TTL</p> <p>Lower Arm Bushing (SMALL)</p>  <p>B : 4 / C : 72 pcs.</p>
<p>D2464WB</p> <p>GA2A 34 46XE, 46YE</p> <p>CRONOS</p> <p>Lower Arm Bushing (BIG)</p>  <p>B : 4 / C : 72 pcs.</p>	<p>D2464WS</p> <p>GA2B 34 470A</p> <p>CRONOS</p> <p>Lower Arm Bushing (SMALL)</p>  <p>B : 8 / C : 144 pcs.</p>
<p>D24A00B</p> <p>B25D 34 460</p> <p>323 SEDAN (2000)</p> <p>Lower Arm Bushing (BIG)</p>  <p>B : 6 / C : 108 pcs.</p>	<p>D24A00S</p> <p>B25D 34 470</p> <p>323 SEDAN (2000)</p> <p>Lower Arm Bushing (SMALL)</p>  <p>B : 8 / C : 144 pcs.</p>
<p>D2437BLZ</p> <p>B455 34 46YA-IN</p> <p>SEDAN (1992)</p> <p>Lower Arm Bushing (LH, Bracket)</p>  <p>B : 2 / C : 32 pcs.</p>	<p>D2437BRZ</p> <p>B455 34 46XA-IN</p> <p>SEDAN (1992)</p> <p>Lower Arm Bushing (RH, Bracket)</p>  <p>B : 2 / C : 32 pcs.</p>
<p>D2438BLZ</p> <p>BC1F 34 46YA-IN</p> <p>SEDAN (1995)</p> <p>Lower Arm Bushing (LH, Bracket)</p>  <p>B : 2 / C : 32 pcs.</p>	<p>D2438BRZ</p> <p>BC1F 34 46XA-IN</p> <p>SEDAN (1995)</p> <p>Lower Arm Bushing (RH, Bracket)</p>  <p>B : 2 / C : 32 pcs.</p>
<p>D24MZ3WB</p> <p>B32H 34 350B, BBM2 34 460</p> <p>MAZDA3 (2003-2012)</p> <p>Lower Arm Bushing (BIG)</p>  <p>B : 2 / C : 36 pcs.</p>	<p>D24MZ3WS</p> <p>B32H 34 350S</p> <p>MAZDA3</p> <p>Lower Arm Bushing (SMALL)</p>  <p>B : 6 / C : 108 pcs.</p>
<p>D24MZ2WB</p> <p>DL33 34 460</p> <p>MAZDA2, FIESTA</p> <p>Lower Arm Bushing (BIG)</p>  <p>B : 4 / C : 72 pcs.</p>	<p>D24MZ2WS</p> <p>DL33 34 470,300B-2</p> <p>MAZDA2, FIESTA</p> <p>Lower Arm Bushing (SMALL)</p>  <p>B : 10 / C : 180 pcs.</p>





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p><b>D24MZ6W0</b> GS1D 34 300, 350 MAZDA6 (2007-2011) Lower Arm Bushing (BIG, LH, RH)</p>  <p>B : 2 / C : 32 pcs.</p>	<p><b>D24E200W</b> S24A 34 470 E2000, E2200 Lower Arm Bushing</p>  <p>B : 4 / C : 72 pcs.</p>
<p><b>D24T20WB</b> E112 34 350C-B TRIBUTE, ESCAPE Lower Arm Bushing (BIG)</p>  <p>B : 4 / C : 72 pcs.</p>	<p><b>D24T20WS</b> E112 34 350C-S, E112 34 470A TRIBUTE, ESCAPE Lower Arm Bushing (SMALL)</p>  <p>B : 8 / C : 144 pcs.</p>
<p><b>D24MZ6WL</b> GS1D 34 350L-IN MAZDA6 (2007-2011) Lower Arm Bushing (LH, Bracket)</p>  <p>B : 2 / C : 24 pcs.</p>	<p><b>D24MZ6WR</b> GS1D 34 300L-IN MAZDA6 (2007-2011) Lower Arm Bushing (RH, Bracket)</p>  <p>B : 2 / C : 24 pcs.</p>
<p><b>D24BT500P</b> UR56 34 470B BT50 PRO (2WD), (4WD) Upper Arm Bushing</p>  <p>B : 6 / C : 108 pcs.</p>	<p><b>D24BT50P</b> UC3C 34 470A BT50 PRO, RANGER (2012) (2WD), (4WD) Upper Arm Bushing</p>  <p>B : 6 / C : 108 pcs.</p>
<p><b>D24BT50W</b> UC3C 34 450A, 460A BT50 PRO (2WD), (4WD) Lower Arm Bushing</p>  <p>B : 4 / C : 72 pcs.</p>	<p><b>D24M309WS</b> BBM2 34 470 MAZDA3 (2009-2012) Lower Arm Bushing</p>  <p>B : 6 / C : 108 pcs.</p>
<p><b>D24M313B</b> B45A 34 460, B45A 34 350-1 MAZDA3 (2013) SKYACTIV, BM, BN, CX5 (2012) Lower Arm Bushing (BIG)</p>  <p>B : 2 / C : 32 pcs.</p>	<p><b>D24M313S</b> KD35 34 470, TK48 34 470, B45A 34 350-2 MAZDA3 (2013) SKYACTIV, BM, BN, CX5 (2012) Lower Arm Bushing (SMALL)</p>  <p>B : 6 / C : 108 pcs.</p>
<p><b>D24MZ2WBR</b> DL33 34 300B-1 MAZDA2 (2007) Upper Arm Bushing (BIG, RH)</p>  <p>B : 4 / C : 72 pcs.</p>	
<p><b>D24M214WB</b> D09H 34 350E-1, DA6A 34 460 MAZDA2 (2014) SKYACTIVE, DJ Lower Arm Bushing (BIG)</p>  <p>B : 2 / C : 36 pcs.</p>	<p><b>D24M214WS</b> D09H 34 350E-2, DA6A 34 470 MAZDA2 (2014) SKYACTIVE, DJ Lower Arm Bushing (SMALL)</p>  <p>B : 6 / C : 108 pcs.</p>





## MAZDA

<p>D2537B B455 28 200B 323 SEDAN (1992) Suspension Bush (BIG)</p>  <p>B : 8 / C : 144 pcs.</p>	<p>D2537L B455 28 620 323 SEDAN (1992) Suspension Bush (LH)</p>  <p>B : 10 / C : 180 pcs.</p>
<p>D2537RG B455 28 600 323 SEDAN (1992) Suspension Bush (RH, LONG)</p>  <p>B : 10 / C : 180 pcs.</p>	<p>D2537RT B455 28 630 323 SEDAN (1992) Suspension Bush (RH, SHORT)</p>  <p>B : 10 / C : 180 pcs.</p>
<p>D2537S B455 28 200A 323 SEDAN (1992) Suspension Bush (SMALL)</p>  <p>B : 8 / C : 144 pcs.</p>	
<p>D25360 B455 39 830 323 SEDAN (1992-1995) Suspension Bush</p>  <p>B : 10 / C : 240 pcs.</p>	<p>D25361 B455 39 820 323 SEDAN (1992-1995), LANTIS Suspension Bush</p>  <p>B : 12 / C : 288 pcs.</p>
<p>D25362 B092 39 811 323 SEDAN (1992-1995) Suspension Rubber</p>  <p>B : 24 / C : 576 pcs.</p>	
<p>D25MZ301 BP4K 28 200H MAZDA3 Suspension Bush</p>  <p>B : 2 / C : 32 pcs.</p>	<p>D25MZ302 BP4K 28 300B MAZDA3 Suspension Bush</p>  <p>B : 10 / C : 180 pcs.</p>
<p>D25MZ303 BP4K 28 C10B MAZDA3 Suspension Bush</p>  <p>B : 10 / C : 180 pcs.</p>	<p>D25MZ304 BP4K 28 500E MAZDA3 Suspension Bush</p>  <p>B : 10 / C : 180 pcs.</p>
<p>D25MZ305 BP4K 28 300S MAZDA3 Suspension Bush</p>  <p>B : 10 / C : 180 pcs.</p>	<p>D25T20E E112 28 460 TRIBUTE, ESCAPE Suspension Bush</p>  <p>B : 6 / C : 108 pcs.</p>





## MAZDA

<p>D256440</p> <p>GA5R 28 200A-S</p> <p>626 (1991-1995)</p> <p>Suspension Bush</p>  <p>B : 6 / C : 108 pcs.</p>	<p>D256441</p> <p>GA5R 28 200A-B</p> <p>626 (1991-1995)</p> <p>Suspension Bush</p>  <p>B : 6 / C : 108 pcs.</p>
<p>D256442</p> <p>G376 28 200B, 250B</p> <p>626 (1989-1991)</p> <p>Suspension Bush (RE)</p>  <p>B : 6 / C : 108 pcs.</p>	<p>D256443</p> <p>G211 28 620B-B, 600B-B</p> <p>626 (1987-1992)</p> <p>Suspension Bush (RE)</p>  <p>B : 8 / C : 144 pcs.</p>
<p>D256444</p> <p>G376 28 250S, 200S</p> <p>626 (1989-1991)</p> <p>Suspension Bush (RE)</p>  <p>B : 8 / C : 144 pcs.</p>	<p>D256445</p> <p>G211 28 620B-S, 600B-S</p> <p>626 (1987-1991)</p> <p>Suspension Bush (RE)</p>  <p>B : 10 / C : 180 pcs.</p>
<p>D25MZ201</p> <p>D651 28 460</p> <p>MAZDA2, FIESTA</p> <p>Suspension Bush (RE)</p>  <p>B : 2 / C : 36 pcs.</p>	<p>D25MP0E</p> <p>LC62 28 460C</p> <p>MPVLW, LW3W</p> <p>Suspension Bush (RE)</p>  <p>B : 4 / C : 72 pcs.</p>
<p>D25T200E</p> <p>EC01 28 690B</p> <p>TRIBUTE, ESCAPE</p> <p>Suspension Bush (RE)</p>  <p>B : 4 / C : 72 pcs.</p>	<p>D25CX1235</p> <p>KD35 28 350-0, KD35 28 621, B45A 28 350-0</p> <p>MAZDA3 (2013) SKYACTIV, BM.BN, CX5 (2012), (2017) KF</p> <p>Suspension Bush (RE)</p>  <p>B : 6 / C : 108 pcs.</p>
<p>D25CX1243</p> <p>KD35 28 430A, B45A 28 430</p> <p>MAZDA3 (2013) SKYACTIV, BM.BN, CX5 (2012), (2017) KF</p> <p>Suspension Bush (RE)</p>  <p>B : 6 / C : 108 pcs.</p>	<p>D25CX1260</p> <p>KD35 28 602, B45A 28 602</p> <p>MAZDA3 (2013) SKYACTIV, BM.BN, CX5 (2012), (2017) KF</p> <p>Suspension Bush (RE)</p>  <p>B : 6 / C : 108 pcs.</p>
<p>D25BT502S</p> <p>U5A2 27 YA2</p> <p>BT50 PRO</p> <p>Cushion Differential Mount</p>  <p>B : 8 / C : 144 pcs.</p>	<p>D25BT503B</p> <p>U5A3 27 YA2</p> <p>BT50 PRO</p> <p>Cushion Differential Mount</p>  <p>B : 2 / C : 36 pcs.</p>
<p>D25BT501</p> <p>U5A1 27 YA2</p> <p>BT50 PRO</p> <p>Cushion Differential Mount</p>  <p>B : 4 / C : 72 pcs.</p>	





## MAZDA

<p>D25A00251</p> <p>B30H 28 250A-1</p> <p>323 SEDAN (2000)</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>	<p>D25A00252</p> <p>B30H 28 250A-2</p> <p>323 SEDAN (2000)</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>
<p>D25A00601</p> <p>BJ3D 28 600A-1</p> <p>323 SEDAN (2000)</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>	<p>D25A00602</p> <p>BJ3D 28 600A-2</p> <p>323 SEDAN (2000)</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>
<p>D25A00621</p> <p>B30K 28 620A-1</p> <p>323 SEDAN (2000)</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>	<p>D25A00622</p> <p>B30K 28 620A-2</p> <p>323 SEDAN (2000)</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>
<p>D25CX1250</p> <p>KD35 28 500, B45A 28 500</p> <p>MAZDA3 (2013) SKYACTIV, BM,BN, CX5 (2012), (2017) KF</p> <p>Suspension Bush (RE)</p>		<p>B : 6 / C : 180 pcs.</p>	<p>D25CX1268</p> <p>KD35 28 68XA-0,68YA-0</p> <p>CX5 (2012) (4WD)</p> <p>Suspension Bush (RE LH,RH)</p>		<p>B : 6 / C : 108 pcs.</p>
<p>D25CX12C1</p> <p>KD35 28 C10-1,450, KB7W 28 C10-1, B45A 28 450, B45C 28 C10-1</p> <p>MAZDA3 (2013) SKYACTIV, BM, BN, CX5 (2012), (2017) KF</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>	<p>D25CX12C2</p> <p>KD35 28 C10-2,480, KB7W 28 C10-2, B45A 28 480, B45C 28 C10-2</p> <p>MAZDA3 (2013) SKYACTIV, BM, BN, CX5 (2012), (2017) KF</p> <p>Suspension Bush (RE)</p>		<p>B : 8 / C : 144 pcs.</p>
<p>D25CX12X1</p> <p>KD35 28 80XE-1, 890, KD31 28 80XC-1</p> <p>CX5 (2012) (2WD), (4WD)</p> <p>Suspension Bush (RE)</p>		<p>B : 2 / C : 36 pcs.</p>	<p>D25CX12X2</p> <p>KD35 28 80XE-2, 860, KD31 28 80XC-2</p> <p>CX5 (2012) (2WD), (4WD)</p> <p>Suspension Bush (RE)</p>		<p>B : 2 / C : 36 pcs.</p>
<p>D25CX12X3</p> <p>KD35 28 80XE-3, 86X, KD31 28 80XC-3</p> <p>CX5 (2012) (2WD), (4WD)</p> <p>Suspension Bush (RE)</p>		<p>B : 2 / C : 36 pcs.</p>	<p>D25CX12X4</p> <p>KD35 28 80XE-4</p> <p>CX5 (2012) (4WD)</p> <p>Suspension Bush</p>		<p>B : 4 / C : 72 pcs.</p>





## MAZDA

<p><b>D26430</b> 3874 28 330, UH71 28 450 B1600, B2200, MAGNUM, FIGHTER Spring Shackle Bush (FR)</p>	 B : 20 / C : 480 pcs.	<p><b>D26BT52F</b> UR58 28 450A BT50 (2WD), (4WD) Spring Shackle Bush (FR)</p>	 B : 6 / C : 108 pcs.
<p><b>D26BT50F</b> UC2R 28 450D BT50 PRO, RANGER (2012) Shock Absorber Bush (FR)</p>	 B : 4 / C : 72 pcs.	<p><b>D26BT500</b> UC2P 34 700A BT50 PRO (4WD), RANGER (2012) Shock Absorber Bush</p>	 B : 8 / C : 144 pcs.
<p><b>D26MZ2E</b> DL33 28 70XF MAZDA2, FIESTA Shock Absorber Bush</p>	 B : 10 / C : 180 pcs.	<p><b>D26MZ3E</b> BRY0 28 910 MAZDA3 Shock Absorber Bush</p>	 B : 10 / C : 180 pcs.
<p><b>D26CX12E</b> KD45 28 910J-1 CX5 (2012) Shock Absorber Bush (RE)</p>	 B : 6 / C : 108 pcs.	<p><b>D26CX1212</b> KD31 32 123 MAZDA3 (2013) SKYACTIV, BM.BN, CX5 (2012) Grommet Steering Bush (RE)</p>	 B : 10 / C : 180 pcs.
<p><b>D26T10F</b> E112 34 156 TRIBUTE, ESCAPE Stabilizer Shaft Bush (FR)</p>	 B : 10 / C : 160 pcs.	<p><b>D26330</b> B001 39 811A 323 XG, XL Suspension Rubber (RE)</p>	 B : 24 / C : 576 pcs.
<p><b>D26MZ020F</b> DN21 34 156 MAZDA2 (2007-2011) DE, FIESTA (5D) SPORT Stabilizer Shaft Bush (FR)</p>	 B : 6 / C : 144 pcs.	<p><b>D26MZ021F</b> AV59 54 84AB, DN24 34 156A MAZDA2 (2007) DE, FIESTA Stabilizer Shaft Bush (FR)</p>	 B : 6 / C : 144 pcs.
<p><b>D26X316E0</b> DD1V 28 700G-0 CX3 (2016) Shock Absorber Bush (RE)</p>	 B : 10 / C : 180 pcs.		












# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D27260 G030 34 157K 626 GLX Stabilizer Link</p>	 <p>B : 10 / C : 120 pcs.</p>
<p>D27320 B097 34 158K 323 GLX Stabilizer Link</p>	<p>D27330 B029 34 159K 323 XG Stabilizer Link</p>  <p>B : 10 / C : 120 pcs.</p>  <p>B : 10 / C : 120 pcs.</p>
<p>D27350 B459 34 158K ASTINA Stabilizer Link</p>	<p>D27430 UB39 34 154K B1600, B2200, MAGNUM Stabilizer Link</p>  <p>B : 10 / C : 120 pcs.</p>  <p>B : 10 / C : 120 pcs.</p>











# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D2733FL</p> <p>GA2A 34 170A</p> <p>323, 626, CRONOS</p> <p>Link Assy (FR, LH)</p>  <p>B : 2 / C : 54 pcs.</p>	<p>D2733FR</p> <p>GA2A 34 150A</p> <p>323, 626, CRONOS</p> <p>Link Assy (FR, RH)</p>  <p>B : 2 / C : 54 pcs.</p>
<p>D2735E</p> <p>BC1D 28 170A</p> <p>323 SEDAN, ASTINA</p> <p>Link Assy (RE)</p>  <p>B : 2 / C : 40 pcs.</p>	<p>D2764E</p> <p>GA2C 28 170B</p> <p>626 CRONOS</p> <p>Link Assy (RE)</p>  <p>B : 2 / C : 90 pcs.</p>
<p>D27A00E</p> <p>B26R 28 170</p> <p>PROTEGE, 323 SEDAN (2000)</p> <p>Link Assy (RE)</p>  <p>B : 2 / C : 40 pcs.</p>	<p>D27A00F</p> <p>B26R 34 170</p> <p>PROTEGE, 323 SEDAN (2000)</p> <p>Link Assy (FR)</p>  <p>B : 2 / C : 40 pcs.</p>
<p>D27A01E</p> <p>B30H 28 170B</p> <p>323 SEDAN (2002)</p> <p>Link Assy (RE)</p>  <p>B : 2 / C : 54 pcs.</p>	<p>D27A01F</p> <p>LC62 34 170B</p> <p>323 SEDAN (2002)</p> <p>Link Assy (FR)</p>  <p>B : 2 / C : 40 pcs.</p>
<p>D2765E</p> <p>GE4T 28 170</p> <p>626 (1997-1999)</p> <p>Link Assy (RE, RH, LH)</p>  <p>B : 2 / C : 40 pcs.</p>	<p>D2766E0</p> <p>GJ6A 28 170B</p> <p>626 (2002)</p> <p>Link Assy (RE)</p>  <p>B : 2 / C : 108 pcs.</p>
<p>D2766FL</p> <p>GJ6A 34 170A</p> <p>626 (2002)</p> <p>Link Assy (FR, LH)</p>  <p>B : 2 / C : 54 pcs.</p>	<p>D2766FR</p> <p>GJ6A 34 150A</p> <p>626 (2002)</p> <p>Link Assy (FR, RH)</p>  <p>B : 2 / C : 54 pcs.</p>
<p>D27MZ3F</p> <p>BP4K 34 170D</p> <p>MAZDA3</p> <p>Link Assy (FR)</p>  <p>B : 2 / C : 32 pcs.</p>	<p>D27MZ3E</p> <p>BP4K 28 170D</p> <p>MAZDA3</p> <p>Link Assy (RE)</p>  <p>B : 2 / C : 90 pcs.</p>
<p>D27M313FL</p> <p>B45A 34 170</p> <p>MAZDA3 (2013) SKYACTIV, BM, BN</p> <p>Link Assy (FR, LH)</p>  <p>B : 2 / C : 32 pcs.</p>	<p>D27M313FR</p> <p>B45A 34 150</p> <p>MAZDA3 (2013) SKYACTIV, BM, BN</p> <p>Link Assy (FR, RH)</p>  <p>B : 2 / C : 32 pcs.</p>
















# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D27BT52E UR58 28 170 BT50 (2WD) Link Assy (RE) B : 2 / C : 40 pcs.</p> 	<p>D27BT54E UR61 28 170 BT50 (4WD) Link Assy (RE) B : 2 / C : 32 pcs.</p> 
<p>D27T1FR E181 34 150 TRIBUTE, ESCAPE (2.3 cc) Link Assy (FR, LH, RH) B : 2 / C : 36 pcs.</p> 	<p>D27T1FL E181 34 170 TRIBUTE, ESCAPE (2.3 cc) Link Assy (FR, LH) B : 2 / C : 36 pcs.</p> 
<p>D27T2FLR E112 34 150 TRIBUTE, ESCAPE (3.0 cc), MAZDA2 (2007) Link Assy (FR, LH, RH) B : 2 / C : 40 pcs.</p> 	
<p>D27MZ6FL GS1D 34 170 MAZDA6 (2007) Link Assy (FR, LH) B : 2 / C : 54 pcs.</p> 	<p>D27MZ6FR GS1D 34 150 MAZDA6 (2007) Link Assy (FR, RH) B : 2 / C : 54 pcs.</p> 
<p>D27MZ6E GS1D 28 170 MAZDA6 (2007) Link Assy (RE, LH, RH) B : 2 / C : 90 pcs.</p> 	
<p>D27B00F S10H 34 150 BONGO FRIENDEE (1995-2005) Link Assy (FR) B : 2 / C : 32 pcs.</p> 	<p>D27B00E S10H 28 170 BONGO FRIENDEE (1995-2005) Link Assy (RE) B : 2 / C : 108 pcs.</p> 
<p>D27CX70E F15134170 CX7, RX8 (2003-2008) Link Assy (RE) B : 2 / C : 54 pcs.</p> 	<p>D27CX9E L206 28 170 CX9 (2007) Link Assy (RE) B : 2 / C : 90 pcs.</p> 
<p>D27MP00F LC70 34 170 MPV (1999-2006) Link Assy (FR, RH, LH) B : 2 / C : 36 pcs.</p> 	<p>D27TA9E T001 28 170B XILENIA-9 TA Link Assy (RE, LH, RH) B : 2 / C : 40 pcs.</p> 












# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA

<p>D27XE09FL T001 34 17XA XEDOS 9 (TA), MILLENIA (1993-2000) Link Assy (FR, LH) B : 2 / C : 90 pcs.</p> 	<p>D27XE09FR T001 34 170A XEDOS 9 (TA), MILLENIA (1993-2000) Link Assy (FR, RH) B : 2 / C : 90 pcs.</p> 
<p>D27RX8ER F151 34 150 RX8 (2003-2008), CX7 (2007) Link Assy (RE, RH) B : 2 / C : 90 pcs.</p> 	<p>D27RX8E0 F151 28 170 RX8 (2003-2008) Link Assy (RE, LH, RH) B : 2 / C : 90 pcs.</p> 
<p>D27CX9FL TD11 34 170A CX9 (2007) Link Assy (FR, LH) B : 2 / C : 54 pcs.</p> 	<p>D27CX9FR TD11 34 150A CX9 (2007) Link Assy (FR, RH) B : 2 / C : 54 pcs.</p> 
<p>D27BT02F UC2R 34 150 BT50 PRO (2WD), RANGER (2012) Link Assy (FR, LH) B : 2 / C : 32 pcs.</p> 	
<p>D27BT504FL UC7C 34 170 BT50 PRO (4WD), RANGER (2012) Link Assy (FR, LH) B : 2 / C : 40 pcs.</p> 	<p>D27BT504FR UC7C 34 150 BT50 PRO (4WD), RANGER (2012) Link Assy (FR, RH) B : 2 / C : 40 pcs.</p> 
<p>D27CX12EL KD31 28 190 MAZDA3 (2013) SKYACTIV, BM.BN, CX5 (2012), (2017) KF, CX8 (2020) KG Link Assy (RE, LH) B : 2 / C : 54 pcs.</p> 	<p>D27CX12ER KD31 28 170 MAZDA3 (2013) SKYACTIV, BM.BN, CX5 (2012), (2017) KF, CX8 (2020) KG Link Assy (RE, RH) B : 2 / C : 54 pcs.</p> 
<p>D27CX12F0 KD35 34 170 CX5 Link Assy (FR) B : 2 / C : 32 pcs.</p> 	
<p>D27M214F DA6A 34 170, DJ35 34 170 MAZDA2 (2007) DE, (2014) SKYACTIVE, DJ, CX3 (2016) DK, ECOSPORT (2013) Link Assy (FR) B : 2 / C : 40 pcs.</p> 	<p>D27M319F0 BCKE 34 170 MAZDA3 (2019), CX-30 (2020) DM Link Assy (FR LH, RH) B : 2 / C : 40 pcs.</p> 





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## MAZDA













\* RBI Center Bearing is assembled with Japanese Bearing

<p>D2845P UB40 34 121 MAGNUM Upper Bumper Bound</p>  <p>B : 20 / C : 480 pcs.</p>	<p>D2845W UB39 34 110 MAGNUM Lower Bumper Bound</p>  <p>B : 6 / C : 72 pcs.</p>
<p>D2841XP UH74 34 120 FIGHTER, RANGER (4WD) Upper Bumper Bound</p>  <p>B : 16 / C : 384 pcs.</p>	<p>D2841XW UH74 34 110 FIGHTER, RANGER (4WD) Lower Bumper Bound</p>  <p>B : 6 / C : 72 pcs.</p>
<p>D28BT54E UH74 28 111A BT50 (4WD) Bumper Bound (RE)</p>  <p>B : 2 / C : 24 pcs.</p>	<p>D28BT50W UC2R 34 110B BT50 PRO (2WD), (4WD) Lower Bumper Bound</p>  <p>B : 6 / C : 72 pcs.</p>
<p>D294X0 SA02 25 310 FIGHTER, RANGER Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>	<p>D29410 0755 25 300 M1200, B2200 Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>
<p>D29450 P030 25 310C MAGNUM Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>	<p>D29460 P047 25 310 THUNDER Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>
<p>D294X4 SA52 25 310 FIGTHER, RANGER (4WD) Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>	
<p>D29BT520 SA12 25 300 BT50 (2WD) Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>	<p>D29BT540 SA68 25 300A BT50 (4WD) Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>
<p>D29BT50 U6A125YA1, JB3Z4W602B, JB3G4W602BA BT50 PRO (2WD,4WD), RANGER (2.0 CC) (2018) Center Bearing</p>  <p>B : 1 / C : 20 pcs.</p>	





## MAZDA

<p><b>D30440</b> 8595 33 651 B2200, FIGHTER Cylinder Piston</p>  <p>B : 1 / C : 60 pcs.</p>	<p><b>D30450</b> H260 33 651 MAGNUM Cylinder Piston</p>  <p>B : 1 / C : 60 pcs.</p>
<p><b>D30470</b> UH71 33 651 FIGHTER, RANGER Cylinder Piston</p>  <p>B : 1 / C : 60 pcs.</p>	<p><b>D30BT50F</b> UCYR 33 65X BT50 PRO, RANGER (2012) Cylinder Piston</p>  <p>B : 1 / C : 60 pcs.</p>
<p><b>D3837L</b> B456 32 124 323 SEDAN (1995) Grommet Steering Rack (LH)</p>  <p>B : 8 / C : 128 pcs.</p>	<p><b>D3838MR</b> B455 32 123 323 SEDAN (1992-1995) Grommet Steering Rack (RH, M/T)</p>  <p>B : 6 / C : 96 pcs.</p>
<p><b>D3838PR</b> B595 32 123 323 SEDAN (1995) Grommet Steering Rack (RH, POWER)</p>  <p>B : 6 / C : 96 pcs.</p>	
<p><b>D3864L</b> GA2A 32 124 CRONOS Grommet Steering Rack (LH)</p>  <p>B : 6 / C : 96 pcs.</p>	<p><b>D3864R</b> GA2A 32 123 CRONOS Grommet Steering Rack (RH)</p>  <p>B : 6 / C : 96 pcs.</p>
<p><b>D4141X01</b> UH74 39 540 FIGHTER (4WD), RANGER Rubber Differential Mount (WITH 1 EDGE)</p>  <p>B : 12 / C : 192 pcs.</p>	<p><b>D4141X02</b> UH74 39 550 FIGHTER (4WD), RANGER Rubber Differential Mount</p>  <p>B : 12 / C : 192 pcs.</p>
<p><b>D4141X03</b> UH74 39 560 FIGHTER (4WD), RANGER Rubber Differential Mount (WITH 2 EDGE)</p>  <p>B : 12 / C : 192 pcs.</p>	

